

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20003328/AQF3E2

Date: 11/08/2020

REFERENCE

| | | | |
|-------------------|-----------------------|------------------|--------------|
| Insured/Claimant: | MICHELLE SAW MEI SIAN | Policy No: | 1900130787 |
| Date of Loss: | 25/02/2020 | Nature of Claim: | OD |
| | | Claim No: | 5072035021SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | | |
|-----------------------------|--|-------------|-------------------|--|
| Reg No: | SMN2956B | | | |
| Make & Model: | AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A) | Engine No: | CVK085761 | |
| Reg. Date: | 31/07/2019 (Man. Year: 2019) | Chassis No: | WAUZZZF5XKA065436 | |
| Colour: | Silver | Odometer: | 13365 km | |
| Engine Capacity: | 1984 cc | | | |
| Market Value/New Car Price: | S\$160,000.00 | | | |
| Sum Insured (S\$): | Market Value/New Car Price | | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 245/40 R18 | Rear Tyre Size: | 245/40 R18 |
| Front Left Side: | Continental 6 mm | Rear Left Side: | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|------------------|------------------|------------------|--------------|
| Parts | 12,094.00 | 6,024.16 | 6,069.84 | 50.19 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 20,032.00 | 10,432.00 | 9,600.00 | 47.92 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 32,126.00 | 16,456.16 | 15,669.84 | 48.78 |
| - Excess (S\$) | 600.00 | 600.00 | 0.00 | 0.00 |
| (S\$) | 31,526.00 | 15,856.16 | 15,669.84 | 49.70 |
| + GST 7.00/7.00% (S\$) | 2,206.82 | 1,109.93 | 1,096.89 | 49.70 |
| Nett Amount (S\$) | 33,732.82 | 16,966.09 | 16,766.73 | 49.70 |

INSPECTION

| | | | |
|-----------------------------|------------|---------------|--|
| Date of Assignment: | 28/02/2020 | | |
| Date Inspected: | 28/02/2020 | Inspected At: | Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 13.0 days | | |

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Repair | 2,385.00 FS | *- FS |
| 2 | 1 | | *REAR BUMPER FIXING PARTS | Not Necessary | 156.00 FS | *- FS |
| 3 | 1 | | *REAR BUMPER SECURING STRIP | Not Necessary | 210.00 FS | *- FS |
| 4 | 1 | | *TRIM MOLDING | Not Necessary | 958.00 FS | *- FS |
| 5 | 1 | | *REAR LIGHT REFLECTOR - RH | Not Necessary | 39.00 FS | *- FS |
| 6 | 1 | | *LED TAIL LIGHT - RH | Cut | 1,076.00 FS | *860.80 FS |
| 7 | 1 | | *TAIL LIGHT TRIM - RH | Not Necessary | 28.00 FS | *- FS |
| 8 | 4 | | *REAR PARKING AID SEAL RING | Not Necessary | 14.00 FS | *- FS |
| 9 | 1 | | *SIDE PANEL - RH | Distorted | 2,354.00 FS | *1,883.20 FS |
| 10 | 1 | | *SIDE WINDOW - RH | Necessary | 676.00 FS | *540.40 FS |
| 11 | 1 | | *OUTER WHEEL HOUSING - RH | Repair | 595.00 FS | *- FS |
| 12 | 1 | | *WHEEL HOUSING LINER - RH | Crumpled | 259.00 FS | *206.80 FS |
| 13 | 1 | | *WHEEL HOUSING LINER ATTACHMENT PARTS | Not Necessary | 86.00 FS | *- FS |
| 14 | 1 | | *SIDE MEMBER TRIM - RH | Deformed | 778.00 FS | *622.00 FS |
| 15 | 1 | | *ATTACHMENT PARTS | Necessary | 123.00 FS | *98.00 FS |
| 16 | 1 | | *SET ADHESIVE TAPES | Necessary | 200.00 FS | *159.60 FS |
| 17 | 1 | | *REAR ALUMINIUM RIM - RH | Cut | 964.00 FS | *770.80 FS |
| 18 | 4 | | *ALUMINIUM RIM RUBBER VALVE | Not Necessary | 13.00 FS | *- FS |
| 19 | 1 | | *ACRYLIC SEALANT | Necessary | 180.00 FS | *180.00 FS |
| 20 | 1 | | *CAVITY WAX | Necessary | 140.00 FS | *140.00 FS |
| 21 | 1 | | *STONE CHIP | Necessary | 180.00 FS | *180.00 FS |
| 22 | 1 | | *METAL FILLER POWDER | Necessary | 280.00 FS | *280.00 FS |
| 23 | 1 | | *1/4 GLASS SEALANT | Necessary | 100.00 FS | *100.00 FS |
| 24 | 1 | | *SUNDRIES | Necessary | 300.00 FS | *2.56 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$) **12,094.00** **6,024.16**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|------------------|------------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE | New | 360.00 | 360.00 |
| 2 | TO RENEW 1/4 GLASS TO FACILITATE FENDER RENEWAL | New | 300.00 | 300.00 |
| 3 | TO INSTALL 1/4 GLASS SOLAR FILM | New | 200.00 | 200.00 |
| 4 | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT | New | 1,400.00 | 1,400.00 |
| 5 | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINERAND DISENGAGE CURTAIN AIRBAG | New | 1,400.00 | 1,400.00 |
| 6 | TO DISMANTLE REAR BUMPER, REAR LID, AND RHS SILL PANEL TRIM. CUT OUT AND WELD RHS REAR FENDER AND RHS WHEEL OUTER WHEEL HOUSING. TO RENEW REAR BUMPER AND RHS SILL PANEL TRIM. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 8,800.00 | 3,000.00 |
| 7 | TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS OUTER WHEEL HOUSING, RHS SILL PANEL TRIM, RHS SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS | New | 7,100.00 | 3,300.00 |
| 8 | TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT | New | 280.00 | 280.00 |
| 9 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| Gross Labour Cost (S\$) | | | 20,032.00 | 10,432.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >