



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. AC2003537  
INV Date 28/04/2020  
Reference CS/SMO20003332/Dqd3n2  
Code SMO



### PROFESSIONAL SERVICE FEE

Vehicle No. FBM 6866L  
Insured Veh. SKH 4575J  
Claim No. CMTD2000910/RUC  
Policy No.  
Accident Date 26/02/2020  
Inspection Date 02/03/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20003332/Dqd3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 28-04-2020		
		Code : SMO		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SKH 4575J	<b>Veh. Inspected</b>	FBM 6866L
	<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	CMTD2000910/RUC	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	YE YONG KANG MELVIN	<b>Assign Date</b>	28/02/2020
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	HONDA CBF 190X	<b>c.c</b>	184
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
	<b>Chassis No.</b>	LALPJL704H3248333	<b>Colour</b>	RED
	<b>Odometer</b>	90717	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	110/70 R17	PIRELLI	3 mm
	<b>L/H Front Tyre</b>			mm
	<b>R/H Rear Tyre</b>	140/70 R17	METZELER	3 mm
	<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND O/S REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	26/02/2020	<b>Inspection Date</b>	02/03/2020
	<b>Survey held at</b>	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>	



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 6866L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	HANDLE BAR	DISTORTED	145.00	145.00
1	LEVER CLUTCH	CUT	75.00	75.00
1	SET FORK TUBE	DISTORTED	480.00	480.00
1	SET BALANCER	N/S CUT / O/S NOT NECESSARY	195.00	97.50
1	SET MIRROR	N/S CUT / O/S NOT NECESSARY	145.00	72.50
1	FRONT MUDGUARD	BROKEN	215.00	215.00
1	HEAD LAMP GUARD	BROKEN	185.00	185.00
1	FRONT RH FOOTREST	NOT NECESSARY	135.00	-
1	FRONT RH FOOTREST RUBBER	NOT NECESSARY	85.00	-
1	FRONT RH FAIRING	TO REPAIR SEE LABOUR	135.00	-
1	RH TANK COVER	NOT NECESSARY	255.00	-
1	FRONT LH LEFT REST	BROKEN	135.00	135.00
1	EXHAUST PIPE	NOT NECESSARY	550.00	-
1	EXHAUST GUARD	NOT NECESSARY	185.00	-
1	REAR TAIL SIDE COVER FAIRING	CUT	195.00	195.00
1	SWING ARM	NOT NECESSARY	450.00	-
1	BRAKE PEDAL	NOT NECESSARY	65.00	-
1	RH CENTRE BODY COVER	NOT NECESSARY	45.00	-
	LESS 10% DISCOUNT		-367.50	-160.00
			3,307.50	1,440.00
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET SIDE BOX (SN)	BROKEN	800.00	700.00
1	SIDE BOX RACK (SN)	BROKEN	135.00	135.00
1	REAR CARRIER BOX (SN)	NOT NECESSARY	450.00	-
			1,385.00	835.00
<b><u>LABOUR</u></b>				
	TOWING FEE.	NOT NECESSARY	40.00	-
	PUTTY & RESPRAY PAINT.		250.00	120.00

Report Ref No. CS/SMO20003332/Dqd3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REPLACE FORK TUBE.		120.00	80.00
	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC. INCLUSIVE OF THE REPAIR OF FRONT RH FAIRING.		280.00	180.00
			690.00	380.00
GRAND TOTAL			5,382.50	2,655.00

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,100.00
--	--	--	--	----------

Report Ref No. CS/SMO20003332/Dqd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.