

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20003337/KEA3Q2  
**Date:** 12/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800123451
<b>Claimant Vehicle No :</b>	SMQ5894K	<b>Insured Vehicle No :</b>	SKH2870U
Date of Loss:	02/02/2020	Nature of Claim:	TP
		Claim No:	7264835129SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMQ5894K</b>		
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Engine No:	G4FGKU473185
Reg. Date:	26/11/2019 (Man. Year: 2019)	Chassis No:	KMHD841CMLU009788
Colour:	Metallic Grey	Odometer:	23726 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 8 mm	Rear Left Side:	Kumho 8 mm
Front Right Side:	Kumho 8 mm	Rear Right Side:	Kumho 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	438.40	438.40	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	940.00	580.00	360.00	38.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,378.40</b>	<b>1,018.40</b>	<b>360.00</b>	<b>26.12</b>
<b>+ GST 7.00/7.00% (S\$)</b>	96.49	71.29	25.20	26.12

<b>Nett Amount (S\$)</b>	<b>1,474.89</b>	<b>1,089.69</b>	<b>385.20</b>	<b>26.12</b>
<b>+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		535.00		
<b>+ Doc/Search Fee (S\$)</b>		31.00		
<b>Nett Liability (S\$)</b>		<b>1,655.69</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,650.00</b>		

**INSPECTION**

Date of Assignment: 27/02/2020

Date Inspected: 27/02/2020

Inspected At:

Chew Goon Motor (AMK)

Blk 10 Ang Mo Kio Industrial Park 2A, #01-15/16 & 17, AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	503.00 FL	*503.00 FL
2	12		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$)					548.00	548.00
- List Item Discount on L Items 20.00/20.00% (\$)					109.60	109.60
Total Parts (\$)					438.40	438.40

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CONDUCT ELECTRICAL CHECK ,TRANSFER REAR BUMPER SENSORS ,TESTING REWIRING ETC	New	30.00	30.00
2	LABOUR CHARGE FOR PARTS REPLACEMENT	New	280.00	180.00
3	TO RESPRAY AFFECTED AREAS (2K-2TONE)	New	480.00	220.00
4	TO RESEAL PAINT PROTECTION (DIAMONDBRITE) TO SPRAY PAINT AREAS	New	150.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>940.00</b>	<b>580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >