Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20003339/KPA3N2

Date: 21/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant SHC5804D Insured Vehicle No: SH8603R

Vehicle No: Insured vehicle No: Sh8003R

Date of Loss: 26/02/2020 Nature of Claim: TP Claim No: MCT20020507

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5804D

Make & Model:

RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR Engine No: M9R8839C002535

(A

Reg. Date: 16/07/2015 (Man. Year: 2015) Chassis No: VF1ABL15AUC281666

Colour: Metallic White/Red Odometer: 605116 km

Engine Capacity: 1995 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Sailun 8 mm Rear Left Side: Sailun 9 mm
Front Right Side: Sailun 8 mm Rear Right Side: Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,274.16	2,753.47	19,520.69	87.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	18,400.00	1,270.00	17,130.00	93.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	40,674.16	4,023.47	36,650.69	90.11
Approved Total (Overridden) (S\$)		3,200.00		
(S\$)	40,674.16	3,200.00	37,474.16	92.13
+ GST 7.00/7.00% (S\$)	2,847.19	224.00	2,623.19	92.13
Nett Amount (S\$)	43,521.35	3,424.00	40,097.35	92.13
+ Car Rental (5.0 x S\$	+ Car Rental (5.0 x S\$96.99/day) (S\$)			
Ne	ett Liability (S\$)	3,908.95		
Global Sum	Settlement (S\$)	3,900.00		

INSPECTION

Date of Assignment: 27/02/2020

Date Inspected: 27/02/2020 Inspected At: Trans-cab Auto Services Pte Ltd

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Apr 2020)

Parts: 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC5804D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Distorted /	411.90 FL	*411.90 FL
				Dented		
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*-FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*-FL
9	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
10	1		*BUMPER BEAM REAR	Bent		*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Distorted		*114.50 FL
12 13	1		*BUMPER BEAM BRACKET RH REAR	Repai	100.90 FL	*- FL *- FL
14	1		*BUMPER BLOCK LH REAR *BUMPER HARNESS REAR	Serviceable Serviceable	75.70 FL 301.10 FL	
15	1					*-FL
16	1 1		*BOOT REAR *BOOT FINISHER	Repair Serviceable	1,677.20 FL 344.70 FL	"-FL *-FL
17	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*-FL
18	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	- F L *- F L
19	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70FL 277.70FL	*-FL
20	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*-FL
21	1		*BOOT BADGE	Not Necessary	95.80 FL	*-FL
22	1		*BOOT STRUT LH	Serviceable	145.10 FL	*-FL
23	1		*BOOT STRUT RH	Serviceable	145.10 FL	*-FL
24	1		*BOOT HINGE LH	Repair	254.20 FL	*-FL
25	1		*BOOT HINGE RH	Repair	253.80 FL	*-FL
26	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	*- FL
27	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
28	1		*BOOT LOCK	Repair	246.60 FL	*-FL
29	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
30	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- FL
31	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	*- FL
32	1		*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*- FL
33	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
34	1		*TAILLAMP RH	Serviceable	401.40 FL	*- FL
35	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
36	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
37	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
38	1		*OUTER PANEL REAR (END PANEL)	Bent		*745.80 FL
39	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
40	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR	Repair	1,229.40 FL	*-FL
			PANEL)			
41	1		*SPARE WHEEL PANEL BRACKET LH	Repair	70.60 FL	*-FL
			Report was unsubmitted during thi	is print-out.		

Adjuster Report Page 4 of 5

43 1 44 1 45 1 46 1 47 1 48 1 48 1 50 1 51 1 552 1 553 1 554 1 556 1	1 1 1 1 1 1 1 1 1 1	*SPARE WHEEL PANEL BRACKET RH *SPARE WHEEL PANEL TRIM *SPARE TYRE BOARD *EXHAUST REAR *EXHAUST CAP REAR *FENDER PANEL INNER TRIM REAR LH *FENDER PANEL REAR LH *WHEELARCH REAR LH	Repair Serviceable Serviceable Repair Repair Serviceable Serviceable	69.20 FL 612.21 FL 680.90 FL 5,263.60 FL 125.40 FL 671.45 FL	*-FL *-FL *-FL *-FL *-FL
44 145 146 147 148 150 150 1551 1552 1555 1555 1556 1556 1556 1556	1 1 1 1 1 1 1 1 1	*SPARE TYRE BOARD *EXHAUST REAR *EXHAUST CAP REAR *FENDER PANEL INNER TRIM REAR LH *FENDER PANEL REAR LH	Serviceable Repair Repair Serviceable	680.90 FL 5,263.60 FL 125.40 FL	*- FL *- FL
145 146 147 148 149 1550 1551 1552 1555 1555 1556 1556 1	1 1 1 1 1 1 1 1	*EXHAUST REAR *EXHAUST CAP REAR *FENDER PANEL INNER TRIM REAR LH *FENDER PANEL REAR LH	Repair Repair Serviceable	5,263.60 FL 125.40 FL	*-FL
46 1 47 1 48 1 50 1 51 1 552 1 553 1 554 1 555 1	1 1 1 1 1 1 1	*EXHAUST CAP REAR *FENDER PANEL INNER TRIM REAR LH *FENDER PANEL REAR LH	Repair Serviceable	125.40 FL	
47 1 48 1 49 1 50 1 55 1 55 1 55 1 55 1 55 1 55 1	1 1 1 1 1 1	*FENDER PANEL INNER TRIM REAR LH *FENDER PANEL REAR LH	Serviceable		*- FL
148 149 149 1550 1551 1552 1553 1554 1555 1556 1	1 1 1 1 1	*FENDER PANEL REAR LH		671.45 FL	
49 1 50 1 51 1 52 1 53 1 54 1 555 1 56 1	1 1 1 1		Serviceable		*-FL
50 1 51 1 52 1 53 1 54 1 55 1 56 1	1 1 1	*WHEELARCH REAR LH		1,933.20 FL	*-FL
51 1 52 1 53 1 54 1 55 1 56 1	1		Serviceable	181.60 FL	*-FL
52 1 53 1 54 1 55 1 56 1	1	*AIR VENT	Serviceable	59.40 FL	*-FL
53 1 54 1 55 1 56 1	-	*SET PARKING AID	Dented / Shorted	700.00 FS	*400.00 FS
54 1 55 1 56 1		*SET REAR BUMPER CLIP	Necessary	Necessary 66.00 FS	
55 1 56 1	1	*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
56 1	1	*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS
	1	*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS
57 1	1	*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*-FS
	1	*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
58 1	1	*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS
59 1	1	*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
60 1	1	*EXHAUST MOUNTING REAR	Not Necessary	-	
61 1	1	*EXHAUST BRACKET REAR	Repair	24.80 FS	*-FS
62 1	1	*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*-FS
63 1	1	*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS
64 1	1	*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*-FS
65 1	1	*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*-FS
66 1	1	*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*-FS
67 1	1	*SPARE TYRE	Serviceable 330.00		*-FS
68 1	1	*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
69 2	2	*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*-FS
70 1	1	*WINDSCREEN MOULDING	Not Necessary	150.00 FS	*-FS
71 1	1	*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*-FS
72 1	1	*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS
73 1	1	*REAR BUMPER PROTECTOR	Necessary	120.00 FS	*30.00 FS
74 1	1	*SET REAR LICENCE PLATE WITH HOLDER	Serviceable 100.00 FS		*-FS
75 1	1	*REAR RENAULT TYRE 215/60/16	Not Necessary	330.00 FS	*-FS
76 1	1	*REAR RENAULT TYRE RIM	Not Necessary 385.00 FS		*-FS
77 1		*FENDER WHEELARCH REAR LH CLIP	Not Necessary		*-FS
78 1	1	FENDER WHEELARCH REAR LH CLIP	riot rioccoodi (35.00 FS	

F=Franchise part. S=SpcNett. L=ListItemDisc.

 Sub Total (\$\$)
 24,394.62
 2,993.30

 - List Item Discount on L Items 10.00/10.00% (\$\$)
 2,120.46
 239.83

Total Parts (S\$) 22,274.16 2,753.47

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	7,500.00	600.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	500.00
4	TO RUST PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
6	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
7	TO REPAIR AND REALIGNB REAR EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
14	TO TRANSFER OF TIRE RIM AND ON WHEEL BALANCING	i New	170.00	0.00
15	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
16	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
17	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
18	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labour	r Cost (S\$)	18,400.00	1,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >