Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003340/UPS3Q2

**Date:** 22/04/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant SLE2095U Insured Vehicle No: SHC8582Z

Vehicle No: SLE20950 Insured vehicle No: SHC85822

Date of Loss: 27/02/2020 Nature of Claim: TP Claim No: MCT20020572

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLE2095U

 Make & Model:
 HONDA VEZEL, 1.5 X CVT (A)
 Engine No:
 L15B4034252

 Reg. Date:
 13/07/2016 (Man. Year: 2015)
 Chassis No:
 RU11114251

 Colour:
 Black
 Odometer:
 73839 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm
Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,530.00	3,809.28	6,720.72	63.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,440.00	1,480.00	2,960.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,970.00	5,289.28	9,680.72	64.67
Approved Total (Overridden) (S\$)		4,200.00		
Nett Amount (S\$)	14,970.00	4,200.00	10,770.00	71.94
+ Car Rental (7.0 x S\$10	00.00/day) (S\$)	700.00		
+ Doc/Se	earch Fee (S\$)	36.45		
Net	tt Liability (S\$)	4,936.45		
Global Sum S	ettlement (S\$)	4,900.00		

**INSPECTION** 

Date of Assignment: 28/02/2020

Date Inspected: 28/02/2020 Inspected At: Nineteen Autowerks Pte Ltd (HQ)

BLK 15 KAKI BUKIT ROAD 4 #01-53

BARTLEY BIZ CENTRE

Singapore 417808

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Apr 2020)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLE2095U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR -R/H	Repair	1,085.70 FL	*-FL
2	1		*FRONT DOOR LOWER RUBBER	Not Necessary	122.70 FL	*-FL
3	1		*FRONT DOOR WEATHERSTRIP	Not Necessary	130.80 FL	*- FL
4	1		*REAR DOOR -R/H	Badly Dented	1,085.50 FL	*930.60 FL
5	1		*REAR DOOR CHECKER	Not Necessary	62.50 FL	*- FL
6	2		*REAR DOOR HINGES	Not Necessary	117.00 FL	*- FL
7	1		*REAR DOOR INNER TRIM BOARD	Deformed / Torn	588.90 FL	*366.50 FL
8	1		*REAR DOOR INNER LOCK	Not Necessary	285.00 FL	*- FL
9	1		*REAR DOOR REGULATOR COME WITH MOTOR	Bent / Jammed	488.80 FL	*325.50 FL
10	1		*REAR DOOR WEATHERSTRIP	Necessary	130.80 FL	*130.80 FL
11	1		*REAR TAILLAMP -R/H	Not Necessary	695.00 FL	*- FL
12	1		*REAR BUMPER	Grazed	950.60 FL	*507.20 FL
13	1		*REAR BUMPER -SIDE	Deep Cut	225.30 FL	*225.30 FL
14	1		*REAR BUMPER SIDE RETAINER	Not Necessary	50.90 FL	*- FL
15	1		*REAR FENDER -R/H	Repair	1,500.70 FL	*- FL
16	1		*REAR FENDER INNER SHIELD	Not Necessary	149.80 FL	*-FL
17	1		*REAR FENDER WHEEL ARCH GARNISH	Grazed	300.70 FL	*300.70 FL
18	1		*REAR WHEEL HUP COME WITH BEARING	Not Necessary	332.50 FL	*-FL
19	1		*REAR SHOCK ABSORBER	Not Necessary	421.00 FL	*-FL
20	1		*REAR AXLE BEAM	Not Necessary	1,513.30 FL	*-FL
21	1		*SET FRONT DOOR BLACK TAPE	Not Necessary	120.00 FS	*-FS
22	1		*ROCKER PANEL SIDE SKIRT -R/H	Deformed / Torn	450.00 FS	*450.00 FS
23	1		*SET REAR DOOR BLACK TAPE	Necessary	120.00 FS	*80.00FS
24	1		*REAR BUMPER LOWER SPOILER	Grazed	500.00 FS	*500.00 FS
25	1		*REAR TYRE	Serviceable	400.00 FS	*-FS
26	1		*REAR WHEEL RIM -R/H	Cut	750.00 FS	*550.00 FS
			Nott I = I intltom Dice		-	

F=Franchise part. S=SpcNett. L=ListItemDisc.

 Sub Total (S\$)
 12,577.50
 4,366.60

 - List Item Discount on L Items 20.00/20.00% (S\$)
 2,047.50
 557.32

0----

Total Parts (S\$) 10,530.00 3,809.28

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	abour Items						
1	TO REMOVE ,REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00			
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	0.00			
3	TO REMOVE AND REFIT REAR UNDERCARRIAGE	New	350.00	0.00			
4	TO CONDUCT WHEEL ALIGNMENT	New	150.00	60.00			
5	TO REMOVE,REFIT DOOR FITTINGS AND REPLACE DAMAGED PARTS ,TRANSFER ALL FITTINGS TO NEW DOOR	New	400.00	60.00			
6	TO APPLY UNDERCOATING	New	180.00	40.00			
7	PANEL BEATING	New	1,600.00	500.00			
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,500.00	800.00			
	Gross Labour Cost (S\$)		4,440.00	1,480.00			

Report was unsubmitted during this print-out.

< END OF ESTIMATES >