

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003341/KGA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SHD56Z **Insured Vehicle No :** SLE2341J

Date of Loss: 26/02/2020 **Nature of Claim:** TP **Claim No:** 7655900309SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD56Z
Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A) **Engine No:** M9R8839C002813
Reg. Date: 23/03/2015 (Man. Year: 2015) **Chassis No:** VF1ABL15AUC281583
Colour: Metallic White/Red **Odometer:** 432649 km
Engine Capacity: 1995 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:**

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 **Rear Tyre Size:** 215/60 R16
Front Left Side: Sailun 9 mm **Rear Left Side:** Sailun 9 mm
Front Right Side: Sailun 9 mm **Rear Right Side:** Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,550.14	4,379.28	8,170.86	65.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,000.00	990.00	13,010.00	92.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,550.14	5,369.28	21,180.86	79.78
Approved Total (Overridden) (S\$)		4,300.00		
(S\$)	26,550.14	4,300.00	22,250.14	83.80
+ GST 7.00/7.00% (S\$)	1,858.51	301.00	1,557.51	83.80
Nett Amount (S\$)	28,408.65	4,601.00	23,807.65	83.80
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$96.99/day) (S\$)		193.98		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,902.43		

INSPECTION

Date of Assignment: 27/02/2020

Date Inspected: 27/02/2020 **Inspected At:**

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
3	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
4	1		*BUMPER RETAINER FRT LH	Serviceable	101.40 FL	*- FL
5	1		*BUMPER RETAINER FRT RH	Serviceable	101.40 FL	*- FL
6	1		*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
7	1		*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
8	1		*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
9	1		*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
10	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
11	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
12	1		*TOW COVER FRT	Serviceable	60.90 FL	*- FL
13	1		*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
14	1		*RADIATOR GRILLE	Cracked	969.90 FL	*969.90 FL
15	1		*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
16	1		*RADIATOR GRILLE FRAME	Cracked	686.00 FL	*686.00 FL
17	1		*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
18	1		*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*- FL
19	1		*HEADLAMP LH	Mtg Cracked	743.60 FL	*743.60 FL
20	1		*HEADLAMP RH	Serviceable	743.60 FL	*- FL
21	1		*HEADLAMP PANEL FRT LH	Repair	127.70 FL	*- FL
22	1		*HEADLAMP PANEL FRT RH	Repair	128.30 FL	*- FL
23	1		*BONNET	Bent	1,312.70 FL	*1,312.70 FL
24	1		*BONNET INSULATOR	Serviceable	294.30 FL	*- FL
25	1		*BONNET STRUT LH	Serviceable	53.30 FL	*- FL
26	1		*BONNET STRUT RH	Serviceable	53.30 FL	*- FL
27	1		*BONNET HINGE LH	Repair	236.50 FL	*- FL
28	1		*BONNET HINGE RH	Repair	237.40 FL	*- FL
29	1		*BONNET LOCK	Repair	152.80 FL	*- FL
30	1		*BONNET CABLE	Serviceable	55.20 FL	*- FL
31	1		*FENDER PANEL FRT LH	Repair	414.40 FL	*- FL
32	1		*WHEELARCH FRT LH	Serviceable	112.30 FL	*- FL
33	1		*FENDER BRACKET LOWER LH	Serviceable	11.80 FL	*- FL
34	1		*FENDER INSULATOR LH	Serviceable	65.50 FL	*- FL
35	1		*FENDER PANEL FRT RH	Repair	437.10 FL	*- FL
36	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
37	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*- FL
38	1		*FENDER INSULATOR RH	Serviceable	66.30 FL	*- FL
39	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
40	1		*WIPER RESERVOIR NECK	Serviceable	29.30 FL	*- FL
41	1		*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	*- FL
42	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL
43	1		*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
44	1		*AIR CLEANER LOWER	Serviceable	271.26 FL	*- FL
45	1		*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
46	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
47	1		*SET BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
48	1		*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
49	1		*BUMPER BRACKET CLIP FRT RH	Not Necessary	12.00 FS	*- FS
50	1		*BUMPER SUPPORT CLIP FRT RH	Not Necessary	10.50 FS	*- FS
51	1		*RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*- FS
52	1		*SET BUMPER GRILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
53	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*SET FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
55	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
56	1		*FRONT RENAULT TYRE 215/60/16	Serviceable	300.00 FS	*- FS
57	1		*FRONT RENAULT TYRE RIM	Serviceable	380.00 FS	*- FS
58	1		*FRONT LICENCE PLATE WITH HOLDER	Dented	80.00 FS	*45.00 FS
59	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
60	1		*SET WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,812.49	4,847.76
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,262.35	468.48
Total Parts (\$\$)	12,550.14	4,379.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	6,000.00	500.00
4	LABOUR CHARGE TO MOUNT DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
5	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO RUST -PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	440.00
Gross Labour Cost (\$\$)			14,000.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >