

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Feb 2020		29 May 2020 15:48 Edit Adj Rpt	S\$5,063.15 Edit Estimates	S\$5,063.15 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	BLUE CAR EAST ASIA PTE LTD								
Vehicle Reg. No.:	SME9660E	Date of Loss:	30/01/2020 09:00 - :59 [15 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200577/C02/TANGHL2	Policy/Cover Note No.:	DMCVSN30233519000						
Vehicle Reg. No. (Insured):	YK8519P	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Indeco Engineers Pte Ltd - Defu (HQ) No. 39 , Defu Lane 12,, 539139 Defu Lane - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 09/06/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS ☐ View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SME9660E (SNM20D200577/C02/TANGHL2)
[YK8519P]**

TP

BLUE CAR EAST ASIA PTE LTD

Jan 30 2020 9:00AM

[-]

Indeco Engineers Pte Ltd - Defu

View

Photos/Images					
			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/06/20 13:36	General View		Load JPG	☒
2	23/06/20 13:36	General View		Load JPG	☒
3	23/06/20 13:36	General View		Load JPG	☒
4	23/06/20 13:36	General View		Load JPG	☒
5	23/06/20 13:36	General View		Load JPG	☒
6	23/06/20 13:36	General View		Load JPG	☒
7	23/06/20 13:36	General View		Load JPG	☒
8	23/06/20 13:36	General View		Load JPG	☒
9	23/06/20 13:36	General View		Load JPG	☒
10	23/06/20 13:36	General View		Load JPG	☒
11	23/06/20 13:36	General View		Load JPG	☒
12	23/06/20 13:36	General View		Load JPG	☒
13	23/06/20 13:36	General View		Load JPG	☒
14	23/06/20 13:36	General View		Load JPG	☒
15	23/06/20 13:36	General View		Load JPG	☒
16	23/06/20 13:36	General View		Load JPG	☒
17	23/06/20 13:36	General View		Load JPG	☒
18	23/06/20 13:36	General View		Load JPG	☒
19	23/06/20 13:36	General View		Load JPG	☒
20	23/06/20 13:36	General View		Load JPG	☒
21	23/06/20 13:36	General View		Load JPG	☒
22	23/06/20 13:36	General View		Load JPG	☒
23	23/06/20 13:36	General View		Load JPG	☒
24	23/06/20 13:36	General View		Load JPG	☒
25	23/06/20 13:36	General View		Load JPG	☒
26	23/06/20 13:36	General View		Load JPG	☒
27	23/06/20 13:36	General View		Load JPG	☒
28	23/06/20 13:36	General View		Load JPG	☒
29	23/06/20 13:36	General View		Load JPG	☒
30	23/06/20 13:36	General View		Load JPG	☒
31	23/06/20 13:36	General View		Load JPG	☒
32	23/06/20 13:36	General View		Load JPG	☒
33	23/06/20 13:36	General View		Load JPG	☒
34	23/06/20 13:36	General View		Load JPG	☒
35	23/06/20 13:36	General View		Load JPG	☒
36	23/06/20 13:36	General View		Load JPG	☒
37	23/06/20 13:36	General View		Load JPG	☒
38	23/06/20 13:36	General View		Load JPG	☒
39	23/06/20 13:36	General View		Load JPG	☒
40	23/06/20 13:36	General View		Load JPG	☒

Photos/Images			3 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	23/06/20 13:36	General View		Load JPG	☒
42	23/06/20 13:36	General View		Load JPG	☒
43	23/06/20 13:36	General View		Load JPG	☒
44	23/06/20 13:36	General View		Load JPG	☒
45	23/06/20 13:44	Dismantled Parts		Load JPG	☒
46	23/06/20 13:44	Dismantled Parts		Load JPG	☒
47	23/06/20 13:44	Dismantled Parts		Load JPG	☒
48	23/06/20 13:44	Dismantled Parts		Load JPG	☒
49	23/06/20 13:44	Dismantled Parts		Load JPG	☒
50	23/06/20 13:44	Dismantled Parts		Load JPG	☒
51	23/06/20 13:44	Dismantled Parts		Load JPG	☒
52	23/06/20 13:44	Dismantled Parts		Load JPG	☒
53	23/06/20 13:44	Dismantled Parts		Load JPG	☒
54	23/06/20 13:44	Dismantled Parts		Load JPG	☒
55	23/06/20 13:44	Dismantled Parts		Load JPG	☒
56	23/06/20 13:44	Dismantled Parts		Load JPG	☒
57	23/06/20 13:44	Dismantled Parts		Load JPG	☒
58	23/06/20 13:44	Dismantled Parts		Load JPG	☒
59	23/06/20 13:45	Dismantled Parts		Load JPG	☒
60	23/06/20 13:45	Dismantled Parts		Load JPG	☒
61	23/06/20 13:45	Dismantled Parts		Load JPG	☒
62	23/06/20 13:45	Dismantled Parts		Load JPG	☒
63	23/06/20 13:45	Dismantled Parts		Load JPG	☒
64	23/06/20 13:45	Dismantled Parts		Load JPG	☒
65	23/06/20 13:45	Dismantled Parts		Load JPG	☒
66	23/06/20 13:45	Dismantled Parts		Load JPG	☒
67	23/06/20 13:45	Dismantled Parts		Load JPG	☒
68	23/06/20 13:45	Dismantled Parts		Load JPG	☒
69	23/06/20 13:45	Dismantled Parts		Load JPG	☒
70	23/06/20 13:45	Dismantled Parts		Load JPG	☒
71	23/06/20 13:45	Dismantled Parts		Load JPG	☒
72	23/06/20 13:45	Dismantled Parts		Load JPG	☒
Documentation			1 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	29/06/20 11:38	SUPPLEMENTARY		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20003344/GTD3S2**Date:** 29/06/2020**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30233519000

Claimant Vehicle No : SME9660E **Insured Vehicle No :** YK8519P

Date of Loss: 30/01/2020 Nature of Claim: TP Claim No: SNM20D200577/C02/TANGHL2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME9660E**

Make & Model: BLUECAR BLUECAR, (A) Engine No: NOENGINE NUMBER

Reg. Date: 24/10/2018 (Man. Year: 2018) Chassis No: VL4BCEB4RJT003363

Colour: White Odometer: 0 km

Engine Capacity: 0 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15

Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,058.20	3,153.15	905.05	22.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,910.00	490.00	20.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,458.20	5,063.15	1,395.05	21.60
+ GST 7.00/7.00% (S\$)	452.07	354.42	97.65	21.60
Nett Amount (S\$)	6,910.27	5,417.57	1,492.70	21.60

INSPECTION

Date of Assignment: 29/05/2020

Date Inspected: 28/02/2020 Inspected At: Indeco Engineers Pte Ltd - Defu (HQ)
No. 39 , Defu Lane 12,
Singapore 539139

Estimated Period of Repair: 10.0 days

Adjuster: XING GUO QIANG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jun 2020)
Parts:	144	BLUECAR BLUECAR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME9660E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID GLASS (WCP)	Smashed	938.00 F	*938.00 F
2	1		*HATCH PINAINFARINA LOGO (WCP)	Necessary	30.00 F	*30.00 F
3	1		*HATCH PINAINFARINA EMBLEM (WCP)	Necessary	59.00 F	*59.00 F
4	4		*BOOT LID GLASS SCREW COVER (WCP)	Missing	20.00 F	*20.00 F
5	4		*BOOT LID GLASS SCREW (WCP)	Missing	8.00 F	*8.00 F
6	1		*BOOT LID GLASS HINGE ASSY (WCP)	Bent	150.00 F	*150.00 F
7	1		*BOOT LID GLASS DAMPER RH (WCP)	Not Necessary	35.00 F	*- F
8	1		*BOOT LID GLASS DAMPER LH (WCP)	Not Necessary	35.00 F	*- F
9	1		*BOOT LID GLASS LOCK (WCP)	Not Necessary	132.00 F	*- F
10	1		*BOOT LID GLASS LOCK CATCH (WCP)	Not Necessary	550.00 F	*- F
11	1		*BOOT LID GLASS CATCH COVER (WCP)	Not Necessary	35.00 F	*- F
12	1		*ROOF PANEL (EXTERIOR) (WCP)	Distorted	541.00 F	*541.00 F
13	1		*ROOF PANEL GARNISH (WCP)	Cracked	103.00 F	*103.00 F
14	10		*ROOF PANEL GARNISH SCREW (WCP)	Necessary	20.00 F	*20.00 F
15	1		*ROOF LINING (INTERIOR) (WCP)	Distorted	120.00 F	*120.00 F
16	1		*THIRD BRAKE LAMP (WCP)	Cracked	124.00 F	*124.00 F
17	1		*REAR WEATHER STRIP (WCP)	Torn	32.00 F	*32.00 F
18	1		*REAR BODY FRAME (INNER & OUTER) (NPA)	Repair	0.00 F	*- F
19	1		*REAR BODY FRAME GARNISH (NPA)	Not Necessary	0.00 F	*- F
20	1		*ROOF PANEL & REAR BODY FRAME RIVET (SMALL) (WCP)	Necessary	120.00 F	*120.00 F
21	1		*ROOF PANEL & REAR BODY FRAME RIVET (BIG) (WCP)	Necessary	70.00 F	*70.00 F
22	1		*FRONT WINDSCREEN MOULDING (WCP)	Necessary	84.00 F	*84.00 F
23	1		*STICKER (BLUESG)	Necessary	50.00 FS	*50.00 FS
24	2		*FRONT WINDSCREEN SEALANT (BLACK)	Necessary	40.00 FS	*40.00 FS
25	2		*ROOF MOULDING SEALANT (BLACK)	Necessary	40.00 FS	*40.00 FS
26	2		*REAR BODY FRAME SEALANT (WHITE)	Necessary	40.00 FS	*40.00 FS
27	1		*IU BRACKET	Necessary	15.00 FS	*15.00 FS
28	1		*SEAL MOULDING HARD TOP CENT RIGHT (WCP)	Deformed	81.00 F	*81.00 F
29	1		*SEAL MOULDING HARD TOP CENT LEFT (WCP)	Deformed	81.00 F	*81.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **3,553.00** **2,766.00**

Report was unsubmitted during this print-out.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE INTERIOR ITEMS INCLUDING SEATS, INTERIOR BODY PANELS & FRONT WINDSCREEN TO ACCOMMODATE REPAIR & REPLACE INTERIOR ROOF LINING, ROOF PANEL (EXTERIOR) & REAR BODY FRAME (INNER & OUTER), BOOT LID AND AFFECTED AREA.	New	1,400.00	1,200.00
2	TO PUTTY AND RESPRAY ON REAR BODY FRAME, ROOF PANEL AND AFFECTED AREA.	New	700.00	600.00
3	TO APPLY TUFF KOTE.	New	200.00	80.00
4	TO CHECK WIRING.	New	100.00	30.00
Gross Labour Cost (\$\$)			2,400.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >