



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 3168Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>			
	SUNDRIES (SN)	NECESSARY	100.00	20.00
			100.00	20.00
	<u>LABOUR</u>			
	TO REPAIR BONNET.		660.00	660.00
	TO RESPRAY BONNET.		630.00	630.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NOT NECESSARY	250.00	-
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NOT NECESSARY	350.00	-
			2,140.00	1,290.00
GRAND TOTAL			2,240.00	1,310.00
RECOMMENDED COST OF REPAIRS				1,310.00

Report Ref No. CS/AWA20003345/Gyd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.