

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

#### **TAX INVOICE**

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE

SINGAPORE 068877

INV No. AC2004656

INV Date 30/06/2020

Reference CC4/FCI20003353/Hea3q2

Code FCI2

#### **PROFESSIONAL SERVICE FEE**

Vehicle No. SKV 2390P

Insured Veh. SHD 6507A

Claim No. D20001204MFSH

Policy No. D-20094922MFSH

Accident Date 25/02/2020

Inspection Date 27/02/2020

| Description                    | Total  |
|--------------------------------|--------|
| Third Party Express Settlement | 500.00 |
| Subtotal                       | 500.00 |
| GST (7%)                       | 35.00  |
| Grand Total                    | 535.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

**LKK Auto Consultants Pte Ltd** 





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

|      | Affiliated to Federation Internationale Des Experts En Automobile   |  |                                |            |  |  |  |  |
|------|---|--|--------------------------------|------------|--|--|--|--|
| MS F | FIRST CAPITAL INSURANCE LTD Ref : CC4/FCI20003353/Hea3q2  |  |                                |            |  |  |  |  |
|      | 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877   |  | Date: 30-06-2020<br>Code: FCI2 |            |  |  |  |  |
| 1.   | 1. Policy Particulars :- THIRD PARTY CLAIM  |  |                                |            |  |  |  |  |
|      | Insured Veh.  | SHD 6507A  | Veh. Inspected                 | SKV 2390P  |  |  |  |  |
|      | Policy No.  | D-20094922MFSH   | Coverage (\$)                  | 0.00       |  |  |  |  |
|      | Claim No.   | D20001204MFSH  | Excess (\$)                    | 0.00       |  |  |  |  |
|      | Assign From   | JOANNE YONG  | Assign Date                    | 27/02/2020 |  |  |  |  |
| 2.   | •   | Vehicle Partic   | culars & Condition             |            |  |  |  |  |
|      | Make & Model  | MERCEDES BENZ  | c.c                            | 1595       |  |  |  |  |
|      | Engine No.  | HIDDEN   | Year of Reg.                   | 2015       |  |  |  |  |
|      | Chassis No.   | WDD1173422N251755  | Colour                         | BLACK      |  |  |  |  |
|      | Odometer  | 62460  | Steering                       | IN ORDER   |  |  |  |  |
|      | Brakes  | IN ORDER   | Modification                   | SPORTS RIM |  |  |  |  |
|      | General   | GOOD   |                                |            |  |  |  |  |
| 3.   | _   | Conditi  | ons of Tyres                   | _          |  |  |  |  |
|      |   | Size   | Make                           | Balance    |  |  |  |  |
|      | R/H Front Tyre  | 235/35Z R19  | HEADWAY                        | 5 mm       |  |  |  |  |
|      | L/H Front Tyre  | 235/35Z R19  | HEADWAY                        | 5 mm       |  |  |  |  |
|      | R/H Rear Tyre   | 235/35Z R19  | HEADWAY                        | 5 mm       |  |  |  |  |
|      | L/H Rear Tyre   | 235/35Z R19  | HEADWAY                        | 5 mm       |  |  |  |  |
| 4.   |   | · ·  | on of Damages                  |            |  |  |  |  |
|      | THE VEHICLE SU  | STAINED DAMAGES AT THE O/S   | BODY.                          |            |  |  |  |  |
|      | DAMAGES SEE D   | ETAILS.  |                                |            |  |  |  |  |
| 5.   |   | Genera   | Information                    |            |  |  |  |  |
|      | Accident Date   | 25/02/2020   | Inspection Date                | 27/02/2020 |  |  |  |  |
|      | Survey held at  | DETAIL LAB   |                                |            |  |  |  |  |
|      |   | BLK 8 KAKI BUKIT AVE 4<br>#02-03/04 PREMIER @ KB<br>SINGAPORE 415875 |                                |            |  |  |  |  |
| 5a.  |   | Re   | emarks                         |            |  |  |  |  |
|      | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                                |            |  |  |  |  |
| 5b.  | <b>5b.</b> Estimate Days of Repair  |  |                                |            |  |  |  |  |
|      | ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days  |  |                                |            |  |  |  |  |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

#### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 2390P

| Qty | Description of Parts   | Condition               | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
|     | REPLACEMENT OF PARTS   |                         |                               |                   |
| 1   | R/H QUARTER PANEL  | TO REPAIR SEE<br>LABOUR | 1,850.00                      | -                 |
| 1   | REAR BUMPER  | TO REPAIR SEE<br>LABOUR | 1,350.00                      | -                 |
| 1   | REAR R/H R DOOR  | BENT                    | 1,250.00                      | 1,250.00          |
| 1   | REAR R/H FRONT DOOR  | TO REPAIR SEE<br>LABOUR | 150.00                        | -                 |
| 1   | REAR R/H REAR DOOR SEAL  | NECESSARY               | 185.00                        | 185.00            |
| 1   | REAR R/H FRONT DOOR SEAL   | NECESSARY               | 185.00                        | 185.00            |
| 1   | REAR R/H SIDE SKIRT R/H  | SCRATCHED               | 455.00                        | 455.00            |
| 1   | REAR R/H WHEEL HUB }   | CRUMPLED                | 368.00                        | 368.00            |
| 1   | REAR R/H WHEEL BEARING }   | CRUSHED                 | -                             | -                 |
|     | LESS 10% DISCOUNT  |                         | -                             | -244.30           |
|     |  |                         | 5,793.00                      | 2,198.70          |
|     | SPECIAL NETT ITEMS   |                         |                               |                   |
| 1   | 19 RIM R/H (SN)  | SCRATCHED               | 1,600.00                      | 700.00            |
| 1   | REAR PDC SENSOR R/H (SN)   | SHORTED                 | 325.00                        | 260.00            |
| 1   | 19 TYRE (SN)   | SERVICEABLE             | 335.00                        | -                 |
|     |  |                         | 2,260.00                      | 960.00            |
|     | LABOUR   |                         |                               |                   |
|     | WHEEL ALIGNMENT.   |                         | 180.00                        | 60.00             |
|     | WIRING CHECK .   |                         | 120.00                        | 30.00             |
|     | REMOVE/REPLACE UNDERCARRIAGE .   |                         | 180.00                        | 100.00            |
|     | TRANSFER DOOR MECHANISM .  |                         | 180.00                        | 70.00             |
|     | SPRAY PAINTING .   |                         | 1,600.00                      | 900.00            |
|     | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER,REAR R/H FRONT DOOR AND R/H QUARTER PANEL . } |                         | 1,300.00                      | 700.00            |
|     | REMOVE/REPLACE RIM 19 . }  |                         | 60.00                         | -                 |
|     | REMOVE/REPLACE PDC SENSOR .  |                         | 80.00                         | 20.00             |
|     |  |                         | 3,700.00                      | 1,880.00          |

Report Ref No. CC4/FCI20003353/Hea3q2



Page No.:2 of 2

| GRAND TOTAL  | 11,753.00 | 5,038.70 |
|--|-----------|----------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) |           | 4,000.00 |

Report Ref No. CC4/FCI20003353/Hea3q2

**LEE HOCK ANN** 

Asst. Automotive Assessor

**HO LEONG CHUAN** 

**Automotive Assessor** 




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION

# PHOTOGRAPHS FOR VEHICLE NO. SKV 2390P















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SKV 2390P

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

# PHOTOGRAPHS FOR VEHICLE NO. SKV 2390P

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315







