

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20003364/GDA3Q2

**Date:** 30/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 09999994017

**Claimant**  
**Vehicle No :** SKW6568M **Insured Vehicle No :** SLA4695X

Date of Loss: 27/02/2020 Nature of Claim: TP Claim No: 1691563807SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW6568M	Engine No:	CRE047618
Make & Model:	AUDI Q7, 3.0 TFSI QU (333 BHP) (A)	Chassis No:	WAUZZZ4M8GD008099
Reg. Date:	30/09/2015 (Man. Year: 2015)	Odometer:	90395 km
Colour:	Black		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	285/45 R20	Rear Tyre Size:	285/45 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,190.00	5,487.68	6,702.32	54.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,752.00	3,652.00	5,100.00	58.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>20,942.00</b>	<b>9,139.68</b>	<b>11,802.32</b>	<b>56.36</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,465.94</b>	<b>639.78</b>	<b>826.16</b>	<b>56.36</b>
<b>Nett Amount (S\$)</b>	<b>22,407.94</b>	<b>9,779.46</b>	<b>12,628.48</b>	<b>56.36</b>
<b>+ Car Rental (5.0 x S\$150.00/day) (S\$)</b>		<b>750.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>7.45</b>		
<b>Nett Liability (S\$)</b>		<b>10,536.91</b>		

### INSPECTION

Date of Assignment: 03/03/2020

Date Inspected: 03/03/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)  
55 UBI ROAD 1  
Singapore 408699

Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,449.00 FS	*1,959.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	420.00 FS	*- FS
3	2		*FRONT BUMPER GUIDE SECTION -LH/RH	Not Necessary	41.00 FS	*- FS
4	1		*FRONT FENDER -LH	Buckled	1,525.00 FS	*1,220.00 FS
5	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	72.00 FS	*- FS
6	1		*FRONT FENDER BRACE -LH	Not Necessary	96.00 FS	*- FS
7	2		*S-LINER INSCRIPTION	Necessary	233.00 FS	*186.40 FS
8	1		*WHEEL HOUSING LINER	Not Necessary	226.00 FS	*- FS
9	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	52.00 FS	*- FS
10	1		*REAR WHEEL HOUSING LINER -LH	Not Necessary	256.00 FS	*- FS
11	2		*FRONT WHEEL COVER-LH/RH	Necessary	1,080.00 FS	*863.20 FS
12	1		*FRONT ALUMINIUM RIM -LH	Cut	1,542.00 FS	*1,233.60 FS
13	1		*FRONT WISHBONE LINK	Not Necessary	388.00 FS	*- FS
14	1		*SUSPENSION GUIDE	Not Necessary	972.00 FS	*- FS
15	1		*GUIDE -LH UPPER FRONT /REAR	Not Necessary	610.00 FS	*- FS
16	1		*WHEEL BEARING HOUSING -LH	Not Necessary	733.00 FS	*- FS
17	1		*SWIVEL JOINT	Not Necessary	208.00 FS	*- FS
18	1		*WHEEL HUB	Not Necessary	460.00 FS	*- FS
19	1		*DOUBLE ANGLED BALL BEARING	Not Necessary	237.00 FS	*- FS
20	1		*TIE ROD END	Not Necessary	190.00 FS	*- FS
21	1		*TYRE (NPA)	Not Necessary	0.00 FS	*- FS
22	1		*SUNDRIES	Necessary	400.00 FS	*25.28 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **12,190.00** **5,487.68**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO RESPRAY FRONT BUMPER ,LOWER SPOILER ,LHS FRONT FENDER AND WHEEL ARCH TRIMS	New	3,000.00	1,500.00
2	TO DISMANTLE LHS FRONT SUSPENSION ASSY .INSPECT FOR DAMAGES AND RENEW ACCORDINGLY	New	2,400.00	0.00
3	TO RENEW LHS FRONT RIM ,CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,FOG LAMPS ,OUTSIDE TEMPERATURE SNESOR ,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
6	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FRONT FENDER RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,400.00	1,200.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,752.00</b>	<b>3,652.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >