

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20003377/KEA3Q2

**Date:** 22/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070004772

**Claimant**  
**Vehicle No :** SCY123L **Insured Vehicle No :** SKZ7066Y

Date of Loss: 22/02/2020 Nature of Claim: TP Claim No: 9595983700SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCY123L		
Make & Model:	FERRARI 458 SPECIALE, 4.5 (A)	Engine No:	254428
Reg. Date:	13/11/2014 (Man. Year: 2014)	Chassis No:	ZFF75VHC000205521
Colour:	Red	Odometer:	31274 km
Engine Capacity:	4497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/35Z R20	Rear Tyre Size:	305/30Z R20
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,058.00	880.00	178.00	16.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	650.00	500.00	43.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,208.00</b>	<b>1,530.00</b>	<b>678.00</b>	<b>30.71</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	154.56	107.10	47.46	30.71
<b>Nett Amount (\$\$)</b>	<b>2,362.56</b>	<b>1,637.10</b>	<b>725.46</b>	<b>30.71</b>
<b>+ Loss of Use (2.0 x S\$180.00/day) (\$\$)</b>		360.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>1,999.10</b>		

### INSPECTION

Date of Assignment: 28/02/2020

Date Inspected: 28/02/2020 Inspected At: Optima Werkz Pte Ltd (HQ)  
6 Kung Chong Road  
Singapore 159143

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 F	*80.00 F
2	1		*SET FRONT BUMPER RIVET	Serviceable	60.00 F	*- F
3	1		*SET FRONT BUMPER GROMMET	Serviceable	118.00 F	*- F
4	1		*FRONT BUMPER PPF PROTECTION FILM STICKER	Necessary	800.00 F	*800.00 F
				<b>Total Parts (S\$)</b>	<b>1,058.00</b>	<b>880.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGES TO REMOVE & REFIX ,REPAIR & READJUST FRONT ACCIDENT AREAS & ETC	New	400.00	250.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT FRONT BUMPER & ETC	New	600.00	400.00
3	TO DIAGNOSE FAULTY CODE & RESET MEMORY	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,150.00</b>	<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >