

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003429/KES3Q2

Date: 10/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900104021

Claimant
Vehicle No : GBH7993Y **Insured Vehicle No :** SKU1626Y

Date of Loss: 28/02/2020 Nature of Claim: TP Claim No: 4029369386SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH7993Y		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5MT 5DR (M)	Engine No:	YD25034383B
Reg. Date:	05/10/2018 (Man. Year: 2018)	Chassis No:	JN1MC2E26Z0030556
Colour:	Metallic Silver	Odometer:	81313 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,932.56	2,133.26	2,799.30	56.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,490.00	1,240.00	250.00	16.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	6,422.56	3,373.26	3,049.30	47.48
+ GST 7.00/7.00% (\$\$)	449.58	236.13	213.45	47.48
Nett Amount (\$\$)	6,872.14	3,609.39	3,262.75	47.48
+ Car Rental (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		8.00		
Nett Liability (\$\$)		4,017.39		

INSPECTION

Date of Assignment: 02/03/2020

Date Inspected: 02/03/2020 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun
Industrial Park A
Singapore 768761

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	571.90 FN	*571.90 FN
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	164.90 FN	*164.90 FN
3	6		*FRONT BUMPER CLIPS	Necessary	30.00 FN	*30.00 FN
4	1		*RH HEADLAMP	Cracked	393.20 FN	*393.20 FN
5	1		*FRONT GRILLE	Serviceable	596.20 FN	*- FN
6	6		*FRONT GRILLE CLIPS	Not Necessary	30.00 FN	*- FN
7	1		*FRONT RH DOOR	Bent	1,071.40 FN	*1,071.40 FN
8	1		*FRONT RH DOOR TOP HINGE	Repair	58.90 FN	*- FN
9	1		*FRONT RH STEP GARNISH TRAY	Serviceable	67.90 FN	*- FN
10	1		*ENGINE RH COOLER	Serviceable	2,121.60 FS	*- FS
11	1		*FRONT RH DOOR COY STICKER	Necessary	20.00 FS	*20.00 FS
12	1		*ENGINE TURBO COOLER GUARD	Dented	105.00 FS	*105.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	5,231.00	2,356.40
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	298.44	223.14
Total Parts (\$\$)	4,932.56	2,133.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER ASSY ,HEADLAMPS,FRT GRILLE RH STEP TRAY ,FRT RH DOOR & ATTACHMENT KNOCK & REPAIR FRT RH W/SCREEN PILLAR ,RH HEADLAMP PANEL & REALIGN THE SAME	New	600.00	500.00
2	REMOVE & REFIX FRT RH DOOR GLASS	New	60.00	60.00
3	PUTTY & RESPRAY ON FRT RH CORNAL GARNISH ,FRT RH DOOR W/SCREEN PILLAR ,STEP GARNISH ,FRT BUMPER	New	800.00	650.00
4	RUSTPROOFING	New	30.00	30.00
Gross Labour Cost (\$\$)			1,490.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >