

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003434/T1DS3Q2

Date: 19/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800045653

Claimant
Vehicle No : SLE5087Z **Insured Vehicle No :** SLZ4316J

Date of Loss: 09/01/2020 Nature of Claim: TP Claim No: 0668696869SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE5087Z		
Make & Model:	TOYOTA SIENTA, 1.5 (A)	Engine No:	2NR8565180
Reg. Date:	25/07/2016 (Man. Year: 2016)	Chassis No:	NSP1707016100
Colour:	Silver	Odometer:	226062 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,800.37	1,686.00	1,114.37	39.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	980.00	520.00	34.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,300.37	2,666.00	1,634.37	38.01
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	4,300.37	2,100.00	2,200.37	51.17
+ GST 7.00/7.00% (S\$)	301.03	147.00	154.03	51.17
Nett Amount (S\$)	4,601.40	2,247.00	2,354.40	51.17
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,599.00		

INSPECTION

Date of Assignment: 02/03/2020

Date Inspected: 02/03/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,879.00 FL	*1,086.00 FL
2	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	54.00 FL	*54.00 FL
3	1		*REAR TAILGATE TOYOTA EMBLEM	Necessary	53.00 FL	*53.00 FL
4	1		*REAR BUMPER CENTER PAD	Cut	90.00 FL	*90.00 FL
5	1		*REAR BUMPER	Deformed	1,257.83 FL	*645.00 FL
6	1		*REVERSE SENSOR	Not Working	240.00 FS	*200.00 FS
7	1		*SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,633.83	2,168.00
- List Item Discount on L Items 25.00/25.00% (\$)	833.46	482.00
Total Parts (\$)	2,800.37	1,686.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE FOR REMOVING REAR TAILGATE AND REAR BUMPER OUT TO FACILITATE REPLACEMENT OF DAMAGED PART	New	600.00	400.00
2	TO RESPRAY REAR BUMPER AND REAR TAILGATE	New	600.00	400.00
3	TRANSFER TAILGATE MECHANISM	New	150.00	60.00
4	REMOVE AND INSTALL REAR TAILGATE WINDSCREEN GLASS	New	150.00	120.00
Gross Labour Cost (S\$)			1,500.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >