

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003435/GKA3Q2

Date: 14/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070016229

Claimant
Vehicle No : PC6310K **Insured Vehicle No :** SMS1964H

Date of Loss: 24/02/2020 Nature of Claim: TP Claim No: 1991218192SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC6310K		
Make & Model:	TOYOTA HIACE, 3.0 COMMUTER GL (A)	Engine No:	1KD2732119
Reg. Date:	04/08/2017 (Man. Year: 2017)	Chassis No:	KDH2230033206
Colour:	Silver	Odometer:	139784 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,295.03	480.75	1,814.28	79.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	400.00	720.00	64.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,415.03	880.75	2,534.28	74.21
+ GST 7.00/7.00% (S\$)	239.05	61.65	177.40	74.21
Nett Amount (S\$)	3,654.08	942.40	2,711.68	74.21
+ Loss of Use (3.0 x S\$110.00/day) (S\$)		330.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,274.40		
Global Sum Settlement (S\$)		1,250.00		

INSPECTION

Date of Assignment: 28/02/2020

Date Inspected: 28/02/2020 Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	471.00 FL	*471.00 FL
2	1		*FRONT BUMPER SIDE RETAINER N/S	Deformed	170.00 FL	*170.00 FL
3	1		*N/S FRONT DOOR	Repair	1,421.68 FL	* - FL
4	1		*N/S HEADLAMP	Not Necessary	930.70 FL	* - FL
5	1		*CORPORATE STICKER	Not Necessary	50.00 FS	* - FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,043.38	641.00
- List Item Discount on L Items 25.00/25.00% (S\$)	748.35	160.25
Total Parts (S\$)	2,295.03	480.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	0.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	0.00
3	TO TRANSFER OF N/S FRONT DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST	New	100.00	0.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	500.00	200.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	350.00	200.00
Gross Labour Cost (S\$)			1,120.00	400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >