



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

AI GAsia Insured's Veh No : SMS1964H
Date of Accident : 24 February 2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Messrs Action Success Transport Service

Acknowledged by Repairer

Signature:

Date:

Date : 25 February 2020

LKK - GNO Q'ing

28/02/2020 1040h.

Estimate To Repair PC6310K - Toyota Hiace Commuter GL 3.0 A

Chassis No : KDH2230033206

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper ✓ at	\$ 471.00
02	1 pc	front bumper side retainer n/s ✓ re.	\$ 170.00
03	1 pc	n/s front door x repair.	\$ 1,421.68
04	1 pc	n/s headlamp X NN	\$ 930.70
			\$ 2,993.38
		Less 25 %	\$ 748.35
			\$ 2,245.04
		<u>SPECIAL NETT ITEMS</u>	
05	1 pc	Corporate sticker X NN	\$ 50.00
			\$ 50.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To rust-proofing of the affected areas.	\$ 120.00 X
02		To check electrical lighting concerned.	\$ 50.00 X
03		To transfer of n/s front door fittings and perform water seepage test.	\$ 100.00 X
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00 200
05		Putty and spray painting of the affected portion.	\$ 350.00 200
			\$ 1,120.00
		Total	\$ 3,415.04

3 Days.
Imp sm repair.
After repair photos.
GNO Q'ing
28/2/19 2020.