

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003438/T1GA3Q2

Date: 28/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SHB5112Y	<b>Insured Vehicle No :</b>	SHA4432K
Date of Loss: 27/02/2020	Nature of Claim: TP	Claim No: MCT20020540

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB5112Y</b>	
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Engine No: 2ZRS101777
Reg. Date:	03/11/2017 (Man. Year: 2017)	Chassis No: JTDKB3FU903573640
Colour:	Maroon	Odometer: 258106 km
Engine Capacity:	1798 cc	
Market Value/New Car Price:	N/A	
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,434.20	1,256.94	1,177.26	48.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,340.00	410.00	930.00	69.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>3,774.20</b>	<b>1,666.94</b>	<b>2,107.26</b>	<b>55.83</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	02/03/2020	
Date Inspected:	02/03/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	1.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2020)
<b>Parts:</b>	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHB5112Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR ASSY RH (DISC 10%)	Cracked	1,307.10 F	*1,176.39 F
2	1		*COVER ,OUTER MIRROR ,RH (DISC 25%)	Missing	107.40 F	*80.55 F
3	1		*DOOR FRT/RH	Not Necessary	894.40 F	*- F
4	1		*STICKER DECAL SMRT (DOOR)	Not Necessary	60.00 F	*- F
5	1		*MIRROR LAMP RH	Not Necessary	65.30 F	*- F
<b>Total Parts (S\$)</b>						<b>2,434.20 1,256.94</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODY WORK	New	338.00	100.00
2	SPRAY PAINT	New	558.00	100.00
3	TO REMOVE & REFIX WING MIRROR	New	120.00	120.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	30.00
6	TO WASH AND VACUUM	New	60.00	0.00
7	TOWING CHARGE	New	84.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,340.00</b>	<b>410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >