



Your Ref : MCT20020260

Date: 12th March 2020

Our Ref : CS/III20003439/Hvf3s2

M/s India International Insurance Pte Ltd

64 Cecil Street

#05-02 IOB Building

Singapore 049711

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE FJ 5419U
ACCIDENT ON 13/02/2020 INSURED VEHICLE SHA 2702U**

Instruction was received to inspect the vehicle Reg. No. FJ 5419U. The inspection was conducted on 02/03/2020 at the premises of M/s Hua Ho Trading, Blk 6 Defu Lane 10 #01-540 Singapore 539537.

The following vehicle information was recorded:

Registration Number	: FJ 5419U
Make/Model	: Yamaha RXZ
Year of Registration	: 1991
Body Colour	: Red
Chassis Number	: 2UX005773
Engine Capacity	: 133 cc
Speedometer Reading	: 67729 km

The vehicle sustained damages at the front portion and o/s body. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 6,000.00(est)
Less: LTA Reimbursement Value (RV)	(S\$ 4,218.00)
Nett Liability	<u>S\$ 1,782.00</u>

Vehicle Inspected By:



LEE HOCK ANN
Asst. Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.