

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20003442/AGQF3E2
Date: 20/05/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713
Claimant Vehicle No : FBD6952T	Insured Vehicle No :	SLP1992D
Date of Loss: 17/02/2020	Nature of Claim:	TP Claim No: 620029

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBD6952T	Engine No:	4S3010160
Make & Model:	YAMAHA X-1R, 135cc (M)	Chassis No:	4S3010160
Reg. Date:	22/06/2009 (Man. Year: 2008)	Odometer:	56113 km
Colour:	White		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,941.00	2,432.90	2,508.10	50.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,040.00	570.00	470.00	45.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,981.00	3,002.90	2,978.10	49.79
Approved Total (Overridden) (S\$)		2,400.00		
Nett Amount (S\$)	5,981.00	2,400.00	3,581.00	59.87

INSPECTION

Date of Assignment:	02/03/2020	
Date Inspected:	03/03/2020 Inspected At:	Jec Auto Service (HQ) 1 KAKI BUKIT AVENUE 6 #02-11, Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 May 2020)	
Parts:	N/A	YAMAHA X-1R 135cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBD6952T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WHEEL FENDER	Cut	70.00 F	*70.00 FL
2	1		*FRONT TYRE	Not Necessary	180.00 FS	*- FS
3	1		*FRONT WHEEL RIM	Not Necessary	350.00 FS	*- FS
4	1		*FRONT FORK ASSY	Bent	590.00 F	*590.00 FL
5	1		*FRONT FORK OIL SEAL	Necessary	50.00 FS	*50.00 FS
6	1		*FRONT FORK BRACKET	Bent	145.00 F	*145.00 FL
7	1		*STEERING CONE AND BEARING	Necessary	75.00 F	*75.00 FL
8	1		*HEADLAMP	Cracked	265.00 F	*265.00 FL
9	1		*HEADLAMP TOP GARNISH (BLACK)	Not Necessary	95.00 F	*- FL
10	2		*FRONT SIDE GARNISH (WHITE)	Cut	210.00 F	*210.00 FL
11	1		*FRONT SIDE GARNISH SIGNAL LAMP	N/S Cut	90.00 F	*45.00 FL
12	1		*HANDLE GRIP	N/S Cut	40.00 F	*20.00 FL
13	2		*FRONT WING MIRROR	N/S Cut / O/S Missing	130.00 F	*130.00 FL
14	1		*BRAKE LEVER	Not Necessary	60.00 FS	*- FS
15	1		*CLUTCH LEVER	Cut	60.00 FS	*60.00 FS
16	1		*HANDLE BAR	Not Necessary	180.00 F	*- FL
17	1		*RADIATOR	Not Necessary	450.00 F	*- FL
18	1		*FRONT BASKET	Distorted	70.00 FS	*70.00 FS
19	1		*SPEEDOMETER	Not Necessary	380.00 F	*- FL
20	1		*FRONT FOOTREST BRACKET	Bent	75.00 F	*75.00 FL
21	1		*FOOT CLUTCH LEVER	Bent	40.00 F	*40.00 FL
22	1		*REAR FOOTREST	N/S Cut	70.00 F	*35.00 FL
23	1		*REAR SEAT CUSHION	Torn	165.00 F	*165.00 FL
24	1		*REAR SEAT SIDE GARNISH (WHITE)	N/S Cut	190.00 F	*95.00 FL
25	1		*REAR EXHAUST PIPE	Repair	320.00 F	*- FL
26	1		*REAR EXHAUST PIPE HEAT SHIELD	Dented	55.00 F	*55.00 FL
27	1		*TAILLAMP	Not Necessary	75.00 F	*- FL
28	1		*BRAKE MASTER PUMP	Damaged	160.00 FS	*160.00 FS
29	1		*BRAKE MASTER PUMP BRACKET	Bent	35.00 FS	*35.00 FS
30	1		*HANDLE BAR BRACKET (BLUE)	Bent	30.00 FS	*30.00 FS
31	1		*BRAKE OIL	Necessary	20.00 FS	*20.00 FS
32	2		*FRONT FOOTREST RUBBER	Cut	56.00 F	*56.00 FL
33	1		*HEADLAMP COWLING	Cut	160.00 F	*160.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,941.00	2,656.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	223.10

Total Parts (\$)	4,941.00	2,432.90
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	250.00
2	SPRAY PAINTING	New	350.00	250.00
3	WIRING	New	50.00	30.00
4	TO STRAIGHTEN BODY CHASSIS	New	250.00	0.00
5	TOWING FEES	New	40.00	40.00
			Gross Labour Cost (S\$)	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >