

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20003443/UGA3Q2

**Date:** 17/04/2020

#### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0001732		
<b>Claimant Vehicle No :</b>	SBY9900M	<b>Insured Vehicle No :</b>	YQ521C		
Date of Loss:	24/02/2020	Nature of Claim:	TP	Claim No:	MFL2020D0000468

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SBY9900M</b>		Engine No:	27492030153857	
Make & Model:	MERCEDES-BENZ E200 (R18), 2.0 (A)		Chassis No:	WDD2120342A979429	
Reg. Date:	06/05/2014 (Man. Year: 2014)		Odometer:	161000 km	
Colour:	Green		Engine Capacity:	1991 cc	
Market Value/New Car Price:	N/A		Sum Insured (S\$):	<b>Market Value/New Car Price</b>	

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,488.80	4,737.16	5,751.64	54.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,310.00	590.00	31.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,388.80</b>	<b>6,047.16</b>	<b>6,341.64</b>	<b>51.19</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>12,388.80</b>	<b>4,800.00</b>	<b>7,588.80</b>	<b>61.26</b>
<b>+ Car Rental (4.0 x S\$128.40/day) (S\$)</b>		513.60		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,321.05</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,320.00</b>		

#### INSPECTION

Date of Assignment:	28/02/2020		
Date Inspected:	03/03/2020	Inspected At:	Super-zee Motor Service (HQ) BLK 14 DEFU LANE 10, #01-402 Singapore 539195
Estimated Period of Repair:	5.0 days		

---

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Mar 2020)	
<b>Parts:</b>	N/A	MERCEDES-BENZ E200 (R18) 2.0 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SBY9900M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER LOWER SPOILER	Torn	278.70 F	*278.70 FL
2	1		*REAR BUMPER LOWER SPOILER CHROME	Cracked	188.40 F	*188.40 FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	896.60 F	*864.60 FL
4	2		*REAR BUMPER RETAINERS	Not Necessary	88.80 F	*- FL
5	1		*REAR BUMPER BRACKETS	O/S Cracked	121.40 F	*60.70 FL
6	1		*REAR BUMPER INNER IMPACT BRACKET	Cracked	278.30 F	*278.30 FL
7	1		*REAR BUMPER }	Distorted	1,815.80 F	*1,798.01 FL
8	1		*REAR BUMPER TOWING COVER }		75.20 F	*- FL
9	10		*REAR BUMPER CLIPS	Necessary	75.00 F	*75.00 FL
10	1		*REAR SWITCH MODULE	Cracked	438.20 F	*438.20 FL
11	1		*REAR SWITCH MODULE SENSORS	Cracked	286.60 F	*286.60 FL
12	1		*REAR BOOTLID	Repair	3,036.70 F	*- FL
13	1		*TAILGATE EMBLEM -LOGO	Necessary	69.40 F	*69.40 FL
14	1		*TAILGATE EMBLEM -E200	Necessary	98.60 F	*98.60 FL
15	1		*TAILGATE EMBLEM -C&C	Necessary	58.90 F	*58.90 FL
16	1		*TAILGATE EMBLEM -7G -TRONIC	Necessary	133.10 F	*133.10 FL
17	1		*REAR END PANEL	Repair	1,254.00 F	*- FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	159.60 F	*- FL
19	1		*EXHAUST CHROME MUFFLER	Bent	395.50 F	*350.00 FL
20	2		*REVERSE SENSORS	Shorted (1 PCS ONLY)	740.00 F	*285.00 FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,488.80</b>	<b>5,263.51</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	526.35
<b>Total Parts (\$\$)</b>	<b>10,488.80</b>	<b>4,737.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANELBEAT WHERE NECESSARY	New	750.00	580.00
2	TO PUTTY ,APPLY PRIMER & SPRAYPAINT AFFECTED PORTION	New	850.00	680.00
3	TO APPLY RUSTPROOFING ON REPAIRED ,REPLACED PANEL	New	200.00	0.00
4	TO CHECK ELECTRICAL WIRING FUNCTIONS & REAR PDC SENSOR	New	100.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,900.00</b>	<b>1,310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >