

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD20003450/UGA3Q2

**Date:** 03/09/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV20019-00018360

**Claimant**  
**Vehicle No :** SMC1303A **Insured Vehicle No :** SKS697J

**Date of Loss:** 27/02/2020 **Nature of Claim:** TP **Claim No:** 1202000010851

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMC1303A</b>	Engine No:	G4LDJD048542
Make & Model:	HYUNDAI I30 PDE, 1.4 T-GDI DCT (A)	Chassis No:	TMAH3813VJJ032684
Reg. Date:	27/06/2018 (Man. Year: 2018)	Odometer:	28950 km
Colour:	Blue		
Engine Capacity:	1353 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,039.80	3,921.40	3,118.40	44.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,460.00	840.00	36.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,339.80</b>	<b>5,381.40</b>	<b>3,958.40</b>	<b>42.38</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,300.00</b>		
<b>(\$\$)</b>	9,339.80	4,300.00	5,039.80	53.96
<b>+ GST 7.00/7.00% (\$\$)</b>	653.79	301.00	352.79	53.96
<b>Nett Amount (\$\$)</b>	<b>9,993.59</b>	<b>4,601.00</b>	<b>5,392.59</b>	<b>53.96</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (\$\$)</b>		500.00		
<b>+ Doc/Search Fee (\$\$)</b>		36.45		
<b>Nett Liability (\$\$)</b>		<b>5,137.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>5,100.00</b>		

### INSPECTION

Date of Assignment: 02/03/2020

Date Inspected: 02/03/2020 Inspected At:

LEE BROTHERS AUTOMOTIVE PTE.  
LTD. (HQ)  
1 Kaki Bukit Ave 6, #02-47 Autobay @  
Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2020)
<b>Parts:</b>	144	HYUNDAI I30 PDE 1.4 T-GDI DCT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMC1303A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	38.00 FL	*38.00 FL
2	1		*REAR TAILGATE	Dented / Bent	2,361.00 FL	*2,361.00 FL
3	1		*REAR TAILGATE RUBBER	Not Necessary	286.00 FL	*- FL
4	1		*REAR TAILGATE LOCK	Not Necessary	151.00 FL	*- FL
5	1		*REAR TAILGATE LOCK CATCH	Not Necessary	32.00 FL	*- FL
6	1		*REAR TAILGATE INNER TRIM	Not Necessary	445.00 FL	*- FL
7	1		*REAR TAILGATE EMBLEM LOGO	Necessary	45.00 FL	*45.00 FL
8	1		*REAR TAILGATE EMBLEM I30	Necessary	38.00 FL	*38.00 FL
9	1		*REAR TAILGATE EMBLEM 1.4T	Necessary	29.00 FL	*29.00 FL
10	1		*REAR TAILGATE REFLECTOR RH(TOP)	Not Necessary	349.00 FL	*- FL
11	1		*REAR TAILGATE REFLECTOR RH(BOTTOM)	Not Necessary	62.00 FL	*- FL
12	1		*REAR TAILLAMP RH	Not Necessary	799.00 FL	*- FL
13	1		*REAR BUMPER (TOP)	Deformed	802.00 FL	*802.00 FL
14	1		*REAR BUMPER (BOTTOM)	Grazed	406.00 FL	*406.00 FL
15	1		*REAR BUMPER REFLECTOR RH	Cracked	79.00 FL	*79.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Cracked	432.00 FL	*432.00 FL
17	1		*REAR BUMPER REINFORCEMENT LOWER BRACKET RH/LH	O/S Bent	70.00 FL	*35.00 FL
18	1		*REAR BUMPER REINFORCEMENT STAY BRACKET RH/LH	O/S Cracked	428.00 FL	*214.00 FL
19	1		*REAR BUMPER SIDE RETAINER RH/LH	O/S Bent	108.00 FL	*54.00 FL
20	1		*REAR END PANEL	Repair	1,321.00 FL	*- FL
21	1		*REAR WINDSCREEN SPONGE TAPE	Necessary	20.00 FS	*20.00 FS
22	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
23	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
24	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,696.00</b>	<b>4,828.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,656.20	906.60
<b>Total Parts (\$\$)</b>	<b>7,039.80</b>	<b>3,921.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO KNOCK OUT DENT ,CUT/WELD REAR PANEL AND REPLACE ACCIDENT PARTS	New	800.00	500.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	New	1,000.00	600.00
3	TO CHECK WIRING	New	20.00	20.00
4	TO REMOVE,REFIX REAR WINDSCREEN	New	120.00	120.00
5	TO TRANSFER REAR TAILGATE PARTS	New	100.00	60.00
6	TO REMOVE ,REFIX CUSHION AND INNER TRIM	New	120.00	80.00
7	TO REMOVE,REPLACE REVERSE SENSOR	New	80.00	50.00
8	TO TUFF KOTE	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,300.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >