

TPAXA.

Cecilia.

SMP 9119U 2009 June

Mercedes Benz C180K. 1597cc

WDD2040452A277266

Front Bumper (After Market) torn	2500(SN) 2000(SN)
Front Bumper Side Holder RH. <i>me</i>	68 ✓
Front Bumper clips. <i>me</i>	30 ✓
Headlamp RH <i>cracked</i>	1195 ✓
Front RH Fender (Aluminium) <i>dented</i>	891 ✓
Front RH Fender Inner Shield <i>torn</i>	232 ✓
Front RH Fender Inner Shield clips. <i>xia</i>	30 ✓
Front RH Wheel Rim. <i>lit</i>	1280 950(SN)
Front RH lower Arm <i>2</i>	475 +
Front RH Knuckle Arm. <i>NP</i>	862 +
Front RH wheel hub Benz <i>me</i>	387 +
Front RH shock Absorber	598 +

2446

SN: 2950

220140

SMP91194.

Panel Beating

~~700~~ 500

Spray Painting.

~~600~~ 500

Wiring.

1110

~~50~~ 30

To perform wheel alignment.

~~150~~ 80

To dismantle front undercarriage,

380X

Total: 6261.40.

L/s: SK

04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: