

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20003454/BES3Q2

**Date:** 22/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100353974

**Claimant**  
**Vehicle No :** SMG5843K **Insured Vehicle No :** SKL2433C

Date of Loss: 27/02/2020 Nature of Claim: TP Claim No: 5852898505SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMG5843K</b>		
Make & Model:	MERCEDES-BENZ 200E, 2.0 (A)	Engine No:	27186030471358
Reg. Date:	01/11/2012 (Man. Year: 2012)	Chassis No:	WDD2120482A640390
Colour:	Beige	Odometer:	146214 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,018.12	3,925.33	6,092.79	60.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,520.00	1,610.00	51.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,148.12</b>	<b>5,445.33</b>	<b>7,702.79</b>	<b>58.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,148.12</b>	<b>4,350.00</b>	<b>8,798.12</b>	<b>66.92</b>
<b>+ Car Rental (7.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		898.80		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>5,285.25</b>		

### INSPECTION

Date of Assignment: 28/02/2020

Date Inspected: 28/02/2020 Inspected At:

160 SIN MING DRIVE #01-14  
Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Estimated Period of Repair: 4.0 days

**Adjuster:** Lim Teow Guan

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Cut	1,058.00 FL	*1,058.00 FL
2	1		*HEADLAMP LOWER BRACKET	No such part	230.00 FL	*- FL
3	1		*FRONT BUMPER	Cut	1,402.50 FL	*1,092.00 FL
4	2		*FRONT BUMPER RETAINER	Not Necessary	172.60 FL	*- FL
5	1		*FRONT BUMPER FOG LAMP LH	Cut	483.90 FL	*217.00 FL
6	1		*FRONT BUMPER FOG LAMP GARNISH LH	Broken	297.60 FL	*158.00 FL
7	1		*FRONT FENDER LH	Bent	947.20 FL	*947.20 FL
8	1		*FRONT FENDER RH INNER SHIELD FRONT	Torn	185.30 FL	*185.30 FL
9	1		*FRONT FENDER RH INNER SHIELD REAR	Not Damaged	198.70 FL	*- FL
10	1		*FRONT FENDER EMBLEM BLUE/EFFICIENCY	Not Necessary	185.00 FL	*- FL
11	1		*WIPER TANK	Not Damaged	310.00 FL	*- FL
12	1		*WIPER TANK MOTOR	Not Damaged	168.00 FL	*- FL
13	1		*FRONT KNUCKLE ARM BEARING LH	Jammed	643.00 FL	*226.20 FL
14	1		*FRONT UPPER ARM LH	Not Damaged	423.00 FL	*- FL
15	1		*FRONT TRUST ARM LH	Not Damaged	410.00 FL	*- FL
16	1		*FRONT LOWER ARM LH	Not Damaged	472.00 FL	*- FL
17	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
18	1		*FRONT BUMPER CLIPS	Not Damaged	60.00 FS	*- FS
19	1		*FRONT ALLOY RIM (LOCAL REPAIR)	Cut	950.00 FS	*200.00 FS
20	1		*FRONT TYRE	Not Damaged	380.00 FS	*- FS
21	1		*FRONT FENDER SEALANT	Not Necessary	100.00 FS	*- FS
22	1		*FRONT FENDER INNER SHIELD FRONT CLIPS	Necessary	60.00 FS	*30.00 FS
23	1		*FRONT FENDER INNER SHIELD REAR CLIPS	Not Necessary	60.00 FS	*- FS
24	1		*FRONT BUMPER SENSOR (6 PCS)	Dislodged (1 PCS ONLY)	1,500.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,776.80</b>	<b>4,313.70</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	758.68	388.37
<b>Total Parts (\$\$)</b>	<b>10,018.12</b>	<b>3,925.33</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	R&R UNDERCARRIAGE	New	180.00	80.00
2	R&R UPHOLSTERY	New	200.00	0.00
3	R&R FRONT BUMPER SENSOR	New	150.00	60.00
4	CONDUCT WHEEL ALIGNMENT	New	120.00	60.00
5	PANEL BEATING	New	1,200.00	800.00
6	SPRAY PAINTING	New	1,000.00	400.00
7	CHECK WIRING	New	80.00	40.00
8	TO RESET AND REPROGRAMME FAULT CODE	New	200.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,130.00</b>	<b>1,520.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >