



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005110
INV Date 21/07/2020
Reference CC3/CTI20003484/Fea3s2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SHC 124R
Insured Veh. SLF 3780M
Claim No. SNM20D201117/C02
Policy No. DMHCSN1907421900
Accident Date 28/02/2020
Inspection Date 02/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC3/CTI20003484/Fea3s2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 21-07-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLF 3780M	Veh. Inspected	SHC 124R	
Policy No.	DMHCSN1907421900	Coverage (\$)	0.00	
Claim No.	SNM20D201117/C02	Excess (\$)	0.00	
Assign From		Assign Date	02/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVLU178652	Colour	YELLOW	
Odometer	60497	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	8 mm	
L/H Front Tyre	195/65 R15	MICHELIN	8 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2020	Inspection Date	02/03/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 124R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	459.40	459.40
1	REAR BUMPER CENTRE - BLACK	CRACKED / DEFORMED	451.25	451.25
1	REAR BUMPER FOGLAMP	CRACKED	201.50	201.50
1	REAR BUMPER BEAM	CRACKED	294.80	294.80
1	REAR BUMPER LWR MOULDING	CRACKED	155.00	155.00
1	REAR BUMPER STAY RH	BENT	138.10	138.10
1	REAR BUMPER STAY LH	NOT NECESSARY	138.10	-
1	REAR BUMPER UNDER COVER	NOT NECESSARY	28.70	-
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	31.90	-
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	31.90	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	SCRATCHED	5.40	5.40
1	TAILGATE ASSY	BUCKLED	2,480.40	2,480.40
1	TAILGATE EMBLEM - HYBRID	NECESSARY	24.30	24.30
1	TAILGATE EMBLEM - IONIQ	NECESSARY	31.30	31.30
	LESS 20% DISCOUNT		-898.81	-852.69
			3,595.24	3,410.76
<u>SPECIAL NETT ITEMS</u>				
1	TALGATE COMFORTDELGRO (SN)	NECESSARY	30.00	30.00
1	TAILGATE 65521111 (SN)	NECESSARY	30.00	30.00
1	TAILGATE APPS (SN)	NECESSARY	40.00	40.00
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSOR (SN)	DAMAGED	135.70	135.70
1	NO PLATE (S)W/TRIM COVER (SN)	CRACKED	55.00	55.00
2	WINDSCREEN ADHESIVE - 310MLC (SN)	NECESSARY	92.00	92.00
			432.70	432.70
<u>LABOUR</u>				
	PANEL BEATING.		700.00	640.00
	SPRAY PAINT CHARGE.		500.00	400.00

Report Ref No. CC3/CTI20003484/Fea3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK ALL LIGHTING.		40.00	40.00
	TUFF COAT ON AFFECTED PARTS.		60.00	60.00
	R/I REVERSE SENSOR.		120.00	60.00
	R/I REAR GLASSES.		200.00	120.00
	TOWING FEE.		60.00	60.00
			1,680.00	1,380.00
GRAND TOTAL			5,707.94	5,223.46
RECOMMENDED COST OF REPAIRS				5,223.46

Report Ref No. CC3/CTI20003484/Fea3s2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.