



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9081P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	TO REPAIR SEE LABOUR	459.40	-
1	REAR BUMPER CENTER -BLACK	SCRATCHED	451.25	451.25
1	REAR BUMPER FOG LAMP	NOT NECESSARY	201.50	-
1	REAR BUMPER BEAM	NOT NECESSARY	294.80	-
1	REAR BUMPER LWR MOULDING	NOT NECESSARY	155.00	-
1	REAR BUMPER STAY RH	NOT NECESSARY	138.10	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	TAILGATE EMBLEM -HYBRID	NECESSARY	24.29	24.29
1	TAILGATE EMBLEM -IONIQ	NECESSARY	31.30	31.30
	LESS 25% DISCOUNT		-444.41	-132.21
			1,333.23	396.63
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE COMFORTDELGRO (SN)	NECESSARY	30.00	30.00
1	TAILGATE 65521111 (SN)	NECESSARY	30.00	30.00
1	TAILGATE APPS (SN)	NECESSARY	40.00	40.00
1	NO PLATE (S)W/TRIM COVER (SN)	NOT NECESSARY	55.00	-
1	TAILGATE ADV.STICKER (SN)	NECESSARY	100.00	100.00
			255.00	200.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER .		700.00	640.00
	SPRAYPAINT CHARGE.		500.00	400.00
	TUFF COAT ON AFFECTED PARTS.		40.00	40.00
	R/I REVERSE SENSOR .		120.00	60.00
			-	-
			-	-
			-	-
			1,360.00	1,140.00
	GRAND TOTAL		2,948.23	1,736.63



RECOMMENDED COST OF REPAIRS			1,736.63
-----------------------------	--	--	----------

Report Ref No. CC3/QBE20003485/Fea3q2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.