

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20003486/QKA3Q2**Date:** 14/07/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700083638
Claimant
Vehicle No : SHD6146H **Insured Vehicle No :** SJJ6679G
Date of Loss: 25/02/2020 Nature of Claim: TP Claim No: 9227502233SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD6146H**
Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR5907074
Reg. Date: 05/10/2015 (Man. Year: 2015) Chassis No: JTDKN36U105766215
Colour: Maroon Odometer: 669719 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,493.65	1,492.16	8,001.49	84.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,001.00	1,130.00	1,871.00	62.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,494.65	2,622.16	9,872.49	79.01
Approved Total (Overridden) (S\$)		2,300.00		
Nett Amount (S\$)	12,494.65	2,300.00	10,194.65	81.59
+ Car Rental (5.0 x S\$111.28/day) (S\$)		556.40		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,863.40		
Global Sum Settlement (S\$)		2,860.00		

INSPECTION

Date of Assignment: 27/02/2020
Date Inspected: 27/02/2020 Inspected At: SMRT Automotive Services Pte Ltd
(Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 3.0 days

Adjuster: OI SUN PIN

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FENDER FRT/RH (DISC 25%)	Dented	723.40 F	*542.55 F	
2	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F	
3	1		*HEAD LAMP RH (DISC 10%)	Scratched	945.20 F	*850.68 F	
4	1		*STICKER DECAL SMRT (DOOR) (SN)	Necessary	60.00 F	*60.00 F	
5	1		*BUMPER FRT	Repair	482.00 F	*- F	
6	1		*WHEEL DISC FRONT	Repair	1,484.20 F	*- F	
7	1		*DOOR FRT /RH	Repair	894.40 F	*- F	
8	1		*BUMPER CLIP	Serviceable	1.61 F	*- F	
9	1		*BUMPER SUPPORT F/RH	Serviceable	76.40 F	*- F	
10	1		*BUMPER SUPPORT F/LH	Serviceable	76.40 F	*- F	
11	1		*BUMPER ENERGY ABSORBER FRT	Serviceable	78.80 F	*- F	
12	1		*BUMPER REINFORCEMENT FRT	Serviceable	498.40 F	*- F	
13	1		*ARM SUB-ASSY ,FR BUMPER LH	Serviceable	250.40 F	*- F	
14	1		*ARM SUB-ASSY ,FR BUMPER RH	Serviceable	250.40 F	*- F	
15	1		*BUMPER GRILLE SUB-ASSY LOWER	Serviceable	311.10 F	*- F	
16	1		*LENS & BODY ,FR TURN RH	Serviceable	511.80 F	*- F	
17	1		*BUMPER LIP FRT	Serviceable	139.60 F	*- F	
18	1		*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F	
19	1		*FENDER PROTECTOR FRT/RH SIDE	Serviceable	113.90 F	*- F	
20	1		*FENDER LINER FRT/RH	Serviceable	171.70 F	*- F	
21	1		*FENDER APRON SUB FRT /RH	Serviceable	637.80 F	*- F	
22	1		*TYRE	Serviceable	126.74 F	*- F	
23	1		*MIRROR ASSY ,RH	Serviceable	1,307.10 F	*- F	
24	1		*MIRROR LAMP RH	Serviceable	65.30 F	*- F	
25	1		*COVER OUTER MIRROR RH	Serviceable	107.40 F	*- F	
					Total Parts (\$\$)	9,493.65	1,492.16

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	507.00	400.00
2	SPRAY PAINT	New	1,674.00	650.00
3	TO REPLACE SUNDRY PARTS	New	100.00	20.00
4	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
5	TO APPLY RUST PROOFING ON AFFECTED AREA	New	100.00	20.00
6	TO WASH AND VACUUM	New	60.00	0.00
7	TO TRANSFER DOOR MECHANISM	New	120.00	0.00
8	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
9	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	20.00
10	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
Gross Labour Cost (\$\$)			3,001.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >