

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20003488/QEA3Q2
Date: 14/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900135303
Claimant Vehicle No :	SMB324B	Insured Vehicle No :	SKV1664G
Date of Loss:	10/10/2019	Nature of Claim:	TP
		Claim No:	5853802772SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMB324B	Engine No:	50330730083077
Make & Model:	MAN NL320F (A22), 10.5 D (M)	Chassis No:	WMAA22ZZ1C7001457
Reg. Date:	16/10/2012 (Man. Year: 2011)	Odometer:	500185 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,676.00	976.00	700.00	41.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	1,676.00	976.00	700.00	41.77
	+ Loss of Use (1.0 x S\$250.00/day) (S\$)	250.00		
	+ Doc/Search Fee (S\$)	7.00		

Nett Liability (S\$) **1,233.00**

INSPECTION

Date of Assignment: 28/02/2020

Date Inspected: 28/02/2020

Estimated Period of Repair: 1.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR FRONT RH PORTION	New	1,060.00	530.00
2	TO PUTTY & RESPRAY	New	616.00	446.00
			Gross Labour Cost (S\$)	976.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >