

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 2084Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	620.90	497.15
2	REAR BUMPER SIDE RETAINER @\$185.45	NOT NECESSARY	370.90	-
10	BUMPER CLIPS @\$12.90	NECESSARY	129.00	50.00
1	BUMPER REFLECTOR (LH)	CRACKED	195.45	195.45
1	BUMPER REINFORCEMENT	NO SUCH PARTS	395.80	-
1	BUMPER SPONGE	NOT FITTED	182.25	-
1	TAILLAMP LOWER BUMPER HOLDER (LH)	NOT NECESSARY	185.45	-
1	BOOTLID	DENTED / BENT	820.45	655.42
2	BOOTLID HINGE @\$185.45	NOT NECESSARY	370.90	-
1	LOCK	SERVICEABLE	395.70	-
1	WEATHERSTRIP	TWISTED	298.70	298.70
1	LOGO	NECESSARY	145.10	65.12
1	VIOS EMBLEM	NECESSARY	145.60	60.80
1	TAILLAMP (LH)	NOT NECESSARY	620.90	-
1	REAR END PANEL	BADLY DENTED	760.35	602.78
	LESS 25% DISCOUNT		-1,409.36	-606.36
			4,228.09	1,819.06
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
	LABOUR			
	TO REMOVE & FIX REVERSE SENSOR .		80.00	50.00
	TO SPRAY ANTI-RUST.		100.00	60.00
	LABOUR CHARGES FOR KNOCKING & REPLACING PARTS.		1,000.00	650.00
	SPRAYPAINTING.		1,200.00	980.00
			2,380.00	1,740.00
	GRAND TOTAL		6,888.09	3,759.06

RECOMMENDED COST OF LUMP SUM REPAIRS		3,000.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/FCI20003495/Uea3q2





Report Ref No. CC4/FCI20003495/Uea3q2

CHUA KANG SENG
Licensed Appraiser