



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2003768
INV Date 11/05/2020
Reference CS/SMO20003496/Dyf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SHA 4997Y
Insured Veh. SKV 6624P
Claim No. CMTD2000834/THE
Policy No.
Accident Date 22/02/2020
Inspection Date 03/03/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20003496/Dyf3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 11-05-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKV 6624P	Veh. Inspected	SHA 4997Y
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000834/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	03/03/2020

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU087881	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/02/2020	Inspection Date	03/03/2020
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 4997Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BONNET	DENTED / BENT	2,265.90	2,265.90
1	BONNET RUBBER (LH)	NOT NECESSARY	15.70	-
1	BONNET RUBBER (RH)	NOT NECESSARY	6.20	-
1	BONNET HINGE (RH)	NOT NECESSARY	82.00	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	7.00	-
1	FRONT BUMPER COVER	DENTED / DISTORTED	1,052.20	1,052.20
1	FRONT BUMPER SPONGE	NOT NECESSARY	99.20	-
1	FRONT BUMPER BRACKET TOP (LH)	NOT NECESSARY	44.80	-
1	FRONT BUMPER BRACKET (LH)	NOT NECESSARY	49.20	-
1	FRONT BUMPER SIDE BRACKET	NOT NECESSARY	4.60	-
1	FRONT BUMPER RETAINER MOUNTING	NOT NECESSARY	8.00	-
1	FRONT BUMPER GRILLE AIR DUCT	NOT NECESSARY	26.20	-
1	HEADLAMP SUPPORT PANEL ASSY	BROKEN	907.40	907.40
2	HEADLAMP (LH/RH)	BROKEN / MOUNTING BROKEN	2,776.00	2,776.00
1	HEADLAMP SUPPORT TOP COVER	BROKEN	222.60	222.60
1	FRONT FENDER (LH)	DENTED	566.30	566.30
1	FRONT FENDER APRON PANEL (LH)	DENTED	637.00	637.00
1	FRONT FENDER SHIELD (LH)	DEFORMED	174.90	174.90
1	FRONT FENDER MUDFLAP (LH)	NOT NECESSARY	13.50	-
1	FRONT FENDER RETAINER	NOT NECESSARY	3.00	-
1	FRONT DOOR MIRROR SIDE GARNISH	NOT NECESSARY	225.00	-
1	FRONT DOOR (LH)	TO REPAIR SEE LABOUR	2,256.40	-
1	FRONT DOOR RUBBER	NOT NECESSARY	96.00	-
1	FRONT DOOR HINGE UPPER (LH)	NOT NECESSARY	44.50	-
1	FRONT DOOR HINGE LOWER (LH)	NOT NECESSARY	44.50	-
1	FRONT DOOR CHECK (LH)	NOT NECESSARY	91.80	-
1	FRONT DOOR TRIM BOARD (LH)	NOT NECESSARY	997.40	-
1	FRONT WINDSCREEN MOULDING	NOT NECESSARY	23.70	-

Report Ref No. CS/SMO20003496/Dyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WINDSCREEN SEALANT	NOT NECESSARY	40.00	-
1	FRONT WINDSCREEN PILLAR OUTER (LH)	NOT NECESSARY	1,535.90	-
2	FRONT WHEEL RIM (LH/RH)	DENTED / BENT	650.60	650.60
2	FRONT WHEEL HUB CAP (LH/RH)	BENT	214.20	214.20
2	FRONT WHEEL NUT (LH/RH) @\$5.70	NOT NECESSARY	11.40	-
2	FRONT WHEEL BEARING (LH/RH) @\$301.80	DAMAGED	603.60	603.60
2	FRONT WHEEL HUB ASSY (LH/RH) @\$153.60	NOT NECESSARY	307.20	-
2	FRONT SHOCK ABSORBER ASSY (LH/RH)	DISTORTED	684.40	684.40
2	FRONT SHOCK ABSORBER MOUNTING (LH/RH) @\$217.60	NOT NECESSARY	435.20	-
2	FRONT DRIVE SHAFT (LH/RH) @\$2061.60	NOT NECESSARY	4,123.20	-
1	RACK & PINION ASSY	DAMAGED	1,820.00	1,820.00
2	STG TIE ROD (LH/RH)	DISTORTED	135.00	135.00
2	STG TIE END (LH/RH)	DISTORTED	125.20	125.20
2	STG BALL JOINT (LH/RH) @\$73.10	NOT NECESSARY	146.20	-
1	STABILIZER BAR	NOT NECESSARY	252.30	-
2	STABILIZER BAR BUSH (LH/RH) @\$16.40	NOT NECESSARY	32.80	-
2	STABILIZER BAR LINK (LH/RH) @\$68.10	NOT NECESSARY	136.20	-
2	STABILIZER BRACKET (LH/RH) @\$24.00	NOT NECESSARY	48.00	-
2	FRONT SUSPENSION LOWER ARM (LH/RH) @\$595.90	DISTORTED	1,191.80	1,191.80
2	KNUCKLE ARM (LH/RH)	DISTORTED	1,104.00	1,104.00
1	WIRING-FRONT	NOT NECESSARY	1,634.00	-
1	RADIATOR GRILLE (ADDITIONAL)	MOUNTING CRACKED	1,480.00	1,110.10
1	ENGINE CROSS MEMBER (ADDITIONAL)	DISTORTED	2,094.40	2,094.40
	LESS 20% DISCOUNT		-6,309.32	-3,667.12
			25,237.28	14,668.48
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR COLOURED COMFORT LOGO (SN)	NECESSARY	75.00	75.00
1	FRONT ERP STICKER (SN)	NOT NECESSARY	26.00	-
1	FRONT TYRE (RH)(50%)(DEPRECIATION)(SN)	CUT	216.00	108.00
			317.00	183.00

Report Ref No. CS/SMO20003496/Dyf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR (LH).		1,600.00	700.00
	SPRAY PAINTING CHARGE.		1,400.00	700.00
	WIRING CHARGE.		180.00	30.00
	TUFF KOTE.		160.00	40.00
	TOWING CHARGE.	NOT NECESSARY	80.00	-
	TRANSFER OF DOOR MECHANISM FRONT.	NOT NECESSARY	80.00	-
	RE-SET FRT POWER WINDOW SYSTEM.	NOT NECESSARY	200.00	-
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE/REFIX UNDERCARRIAGE (FRT).		400.00	300.00
	RE-SET FRT ABS SYSTEM.		200.00	150.00
	REMOVE/REFIX RADIATOR.	NOT NECESSARY	90.00	-
	REMOVE/REFIX AIRCON & REFILL GAS.	NOT NECESSARY	130.00	-
	REMOVE/REFIX FUSE BOX.	NOT NECESSARY	120.00	-
	REMOVE/REFIX FRONT WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	REMOVE/REFIX ENGINE.	NOT NECESSARY	1,200.00	-
			6,080.00	1,980.00
	GRAND TOTAL		31,634.28	16,831.48
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,000.00

Report Ref No. CS/SMO20003496/Dyf3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.