



Your Ref : S0M02HRQ

Date: 18<sup>th</sup> March 2020

Our Ref : CS/ASM20003497/Qqf3e2

**M/s AXA Insurance Pte Ltd**

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn: Jas Tan

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE PA 6846S  
ACCIDENT ON 24/02/2020**

Instruction was received to inspect the vehicle Reg. No. PA 6846S. The inspection was conducted on 03/03/2020 at the premises of M/s SC Auto Industries (S) Pte Ltd, 51, Senoko Road, Singapore 758133.

The following vehicle information was recorded:

Registration Number	: PA 6846S
Make/Model	: Isuzu LT134P
Year of Registration	: 2007
Body Colour	: Multi colour
Chassis Number	: JALLT134P77000101
Engine Capacity	: 7790 cc
Speedometer Reading	: NIL


The Vehicle Caught Fire. The Cause Of Fire Probably Due To Electrical Short Circuit.  
(Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Market Value	S\$ 26,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 8,151.00)
Nett Liability	<u>S\$ 17,849.00</u>

Vehicle Inspected By:

  
OI SUN PIN  
Asst. Automotive Assessor

  
K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MII(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),  
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.