Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003505/APA3Q2

Date: 25/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant Vehicle No: SMM8334L Insured Vehicle No: SH7942T

enicie No.

Date of Loss: 23/02/2020 Nature of Claim: TP Claim No: MCT20020528

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMM8334L

 Make & Model:
 HONDA VEZEL, 1.5 X CVT (A)
 Engine No:
 L15B5569456

 Reg. Date:
 16/07/2019 (Man. Year: 2019)
 Chassis No:
 RU11319417

 Colour:
 Black
 Odometer:
 10917 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,567.60	3,245.92	2,321.68	41.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	730.00	1,860.00	71.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,157.60	3,975.92	4,181.68	51.26
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	8,157.60	3,200.00	4,957.60	60.77
+ Car Rental (3.0 x S\$1	00.00/day) (S\$)	300.00		
+ Doc/S	29.00			
Ne	tt Liability (S\$)	3,529.00		
Global Sum S	3,520.00			

INSPECTION

Date of Assignment: 03/03/2020

Date Inspected: 10/03/2020 Inspected At: Ace Autolution Pte Ltd (KAKI BUKIT)

13 Kaki Bukit Road 4, #03-29/30

Bartley Biz Centre Singapore 417807

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Sep 2020)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMM8334L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	815.00 FL	*815.00 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	570.00 FL	*321.00 FL
3	1		*FRONT BUMPER REINFORCEMENT GARNISH	Not Necessary	170.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RETAINER RH	Not Necessary	108.00 FL	*- FL
5	1		*FRONT BUMPER CHROME	Not Necessary	325.00 FL	*-FL
6	1		*FRONT BUMPER TOW COVER	Not Necessary	56.80 FL	*- FL
7	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	341.20 FL	*- FL
8	1		*FRONT BUMPER FOG LAMP BRACKET RH	Not Necessary	69.60 FL	*- FL
9	1		*FRONT GRILLE	Cracked	428.00 FL	*383.00 FL
10	1		*FRONT GRILLE OUTER CHROME	Cracked	412.60 FL	*412.60 FL
11	1		*FRONT GRILLE OUTER CHROME LOGO	Necessary	58.00 FL	*58.00 FL
12	1		*FRONT HEADLAMP LH	Cracked	1,827.80 FL	*1,827.80 FL
13	1		*FRONT HEADLAMP BRACKET LH	Cracked	65.00 FL	*65.00 FL
14	1		*FRONT BONNET	Not Necessary 1,350.00 FL		*- FL
15	1		*FRONT GRILLE LOGO	Necessary	45.00 FL	*45.00 FL
16	1		*AIRCON CONDENSER SIDE GUIDE	Deformed	55.00 FL	*55.00 FL
17	1		*FRONT GRILLE CLIPS	Necessary	80.00 FS	*30.00 FS
18	1		*FRONT HEADLAMP CLIPS	Not Necessary 80.00 FS		*-FS
19	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
F=Fra	anchise	part. S=Spc				
				Sub Total (S\$)		4,042.40
	- List Item Discount on L Items 20.00/20.00% (S\$)			1,339.40	796.48	
				Total Parts (S\$)	5,567.60	3,245.92

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO REMOVE THE AFFECTED PARTS & FITTNGS TO CONNENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,200.00	400.00				
2	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY RESPRAY PAINT ON PARTS REPLACED	New	1,000.00	300.00				
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	150.00	30.00				
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	120.00	0.00				
5	TO REMOVE AND REPLACE FRONT HEADLAMP	New	120.00	0.00				
	Gross Labour Cost (S\$)		2,590.00	730.00				
	Report was unsubmitted during this print-out.							

< END OF ESTIMATES >