Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003521/KRS3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900141709

Claimant Vehicle No: SJZ1787B Insured Vehicle No: SMN4202E

Date of Loss: 17/11/2019 Nature of Claim: TP Claim No: 0897648942SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJZ1787B

Make & Model: TOYOTA HARRIER 2.0, 2.0 PREMIUM AT AIRBAG Engine No: 3ZRB609541

2WD (A)

Reg. Date: 23/09/2015 (Man. Year: 2015) Chassis No: ZSU600052303

Colour: Metallic Silver Odometer: 54744 km

Engine Capacity: 1986 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18 Rear Tyre Size: 235/60 R18
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,759.10	1,618.35	1,140.75	41.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	850.00	480.00	36.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,089.10	2,468.35	1,620.75	39.64
+ GST 7.00/7.00% (S\$)	286.24	172.78	113.46	39.64
Nett Amount (S\$)	4,375.34	2,641.13	1,734.21	39.64
+ Car Rental (3.0 x S	6160.00/day) (S\$)	480.00		
+ Doc	/Search Fee (S\$)	2.00		

+ Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 3,123.13

Global Sum Settlement (S\$) 3,100.00

INSPECTION

Date of Assignment: 02/03/2020

Date Inspected: 02/03/2020 Inspected At: K.kim Hin Auto Pte Ltd (Autocity)

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming Autocity Singapore 575722

Estimated Period of Repair: 3.0 days

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=... 30/12/2020

Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount		
1	1		*REAR BUMPER	Repair	1,395.30 FL	*- FL		
2	1		*N/S REAR BUMPER SIDE RETAINER	Serviceable	75.70 FL	*- FL		
3	10		*REAR BUMPER CLIPS	Not Necessary	50.00 FL	*- FL		
4	1		*N/S REAR RIM	Dented	2,157.80 FL	*2,157.80 FL		
F=Franchise part. L=ListItemDisc.								
				Sub Total (S\$)	3,678.80	2,157.80		
- List Item Discount on L Items 25.00/25.00% (S\$)					919.70	539.45		
				Total Parts (S\$)	2,759.10	1,618.35		
Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	<u>Labour Items</u>						
1	TO REMOVE ,CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS	New	450.00	250.00			
2	TO CONDUCT REAR WHEEL ALIGNMENT TEST	New	80.00	0.00			
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	800.00	600.00			
	Gross Labour Cost (S\$)		1,330.00	850.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >