

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20003524/EES3Q2**Date:** 26/06/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900164250
Claimant
Vehicle No : SFK8833G **Insured Vehicle No :** SMP2717P
Date of Loss: 01/03/2020 Nature of Claim: TP Claim No: 1571381139SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFK8833G**
Make & Model: BMW X3, 2.0 (A) Engine No: F4203085B48B20B
Reg. Date: 22/10/2018 (Man. Year: 2018) Chassis No: WBATR92000LE25897
Colour: Blue Odometer: 7523 km
Engine Capacity: 1998 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45 R20 Rear Tyre Size: 245/45 R20
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 9,561.80 | 5,309.85 | 4,251.95 | 44.47 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 8,719.00 | 6,967.00 | 1,752.00 | 20.09 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 18,280.80 | 12,276.85 | 6,003.95 | 32.84 |
| + GST 7.00/7.00% (S\$) | 1,279.66 | 859.38 | 420.28 | 32.84 |
| Nett Amount (S\$) | 19,560.46 | 13,136.23 | 6,424.23 | 32.84 |
| + Loss of Use (6.0 x S\$100.00/day) (S\$) | | 600.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 13,738.23 | | |

INSPECTION

Date of Assignment: 03/03/2020
Date Inspected: 03/03/2020 Inspected At: PERFORMANCE MOTORS LTD
303 ALEXANDRA ROAD
SINGAPORE 159941
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *SUNDRIES | Necessary | 150.00 FS | *150.00 FS |
| 2 | 1 | | *DISK WHEEL | Not Necessary | 1,457.45 FS | *- FS |
| 3 | 1 | | *FRT RH DOOR | Dented | 1,538.20 FS | *1,538.20 FS |
| 4 | 1 | | *FRT RH SIDE PANEL | Dented | 848.45 FS | *848.45 FS |
| 5 | 1 | | *FRT RH 1 SIDE PANEL BRACKET | Not Necessary | 35.10 FS | *- FS |
| 6 | 1 | | *RH BOTTOM SIDE PANEL BRACKET | Bent | 35.10 FS | *35.10 FS |
| 7 | 1 | | *FRT RH 2 SIDE PANEL BRACKET | Not Necessary | 35.10 FS | *- FS |
| 8 | 1 | | *FRT RH 3 SIDE PANEL BRACKET | Not Necessary | 35.10 FS | *- FS |
| 9 | 1 | | *FRT RH FOG LAMP SUPPORT | Not Necessary | 65.00 FS | *- FS |
| 10 | 1 | | *FRT BUMPER PANEL PRIMED (M/ICAM) | Repair | 1,679.10 FS | *- FS |
| 11 | 1 | | *SET MOUNTING PDC/PMA SENSOR FRT (M) | Not Necessary | 135.05 FS | *- FS |
| 12 | 1 | | *FRT RH DOOR PROT STRIP PRIMED (M) | Repair | 151.20 FS | *- FS |
| 13 | 1 | | *FRT RH SIDE PANEL FINISHER (M) | Cut | 81.05 FS | *81.05 FS |
| 14 | 1 | | *FRT RH WHEEL ARCH TRIM PRIMED (M) | Cut | 281.35 FS | *281.35 FS |
| 15 | 1 | | *RH SILL TRIM PRIMED (M LIGHT) | Not Necessary | 424.40 FS | *- FS |
| 16 | 1 | | *FRT LH WHEEL ARCH TRIM (M) | Not Necessary | 234.45 FS | *- FS |
| 17 | 3 | | *EXPANDING NUT | Necessary | 6.30 FS | *6.30 FS |
| 18 | 1 | | *ALLOY RIM 8JX20 DOUBLE SPK 699M | Cut | 1,864.35 FS | *1,864.35 FS |
| 19 | 1 | | *EMBLEM (M) | Cut | 82.35 FS | *82.35 FS |
| 20 | 1 | | *(S/L) DOOR WEATHERSTRIP | Necessary | 160.25 FS | *160.25 FS |
| 21 | 20 | | *EXPANDING RIVET BLACK | Necessary | 28.00 FS | *28.00 FS |
| 22 | 1 | | *FRT RH WHEEL ARCH TRIM (M) | Cut | 234.45 FS | *234.45 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$) **9,561.80** **5,309.85**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|---|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS | New | 531.00 | 531.00 |
| 2 | REPLACE FRONT BUMPER INCLUDING ATTACHMENT ,FRONT RIGHT FENDER FRONT RIGHT WHEEL ARCH ,FRONT RIGHT DOOR | New | 4,275.00 | 2,550.00 |
| 3 | PAINTING FRONT BUMPER ,FRONT RIGHT SIDE PANEL ,FRONT RIGHT WHEEL ARCH ,FRONT RIGHT DOOR ,FRONT RIGHT DOOR COVER | New | 3,406.00 | 3,406.00 |
| 4 | TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS | New | 177.00 | 150.00 |
| 5 | TO REPLACE WHEEL RIM INCLUDING BALANCING | New | 94.00 | 94.00 |
| 6 | TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL -2X) | New | 236.00 | 236.00 |
| | | | Gross Labour Cost (\$\$) | 8,719.00 |
| | | | | 6,967.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >