

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003530/EDA3Q2

Date: 14/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800058823

Claimant
Vehicle No : SFC6698K **Insured Vehicle No :** SMA471P

Date of Loss: 02/03/2020 Nature of Claim: TP Claim No: 8473728003SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFC6698K	Engine No:	F4493373B48B20A
Make & Model:	BMW X3, 2.0 xDrive20i (A)	Chassis No:	WBATR120209A50528
Reg. Date:	31/10/2019 (Man. Year: 2019)	Odometer:	3974 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,963.90	1,839.10	124.80	6.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,934.00	556.00	22.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$)	4,453.90	3,773.10	680.80	15.29
+ GST 7.00/7.00% (\$)	311.77	264.12	47.65	15.28
Nett Amount (\$)	4,765.67	4,037.22	728.45	15.29
+ Loss of Use (3.0 x S\$100.00/day) (\$)		300.00		
+ Doc/Search Fee (\$)		2.00		
Nett Liability (\$)		4,339.22		

INSPECTION

Date of Assignment: 03/03/2020

Date Inspected: 17/03/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	10		*EXPANDING RIVET	Not Necessary	26.50 FS	*- FS
3	1		*RH BUMPER GUIDE	Not Necessary	70.30 FS	*- FS
4	1		*REAR BUMPER PANEL PRIMED (BA)	Cut	1,555.40 FS	*1,555.40 FS
5	1		*EXPANDING RIVET BLACK (30 PCS)	Necessary (10 PCS ONLY)	42.00 FS	*14.00 FS
6	1		*REAR RH WHEEL ARCH TRIM	Cut	189.70 FS	*189.70 FS
Total Parts (S\$)					1,963.90	1,839.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,REAR RIGHT WHEEL ARCH COVER INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$)			2,490.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >