

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315 idac

Page No.:1 of 2

Reg. No: 52983356E GST Reg. No. 20-0405911-H

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4198B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, FR BUMPER (DISC 25%)	CUT	495.50	371.63
1	SUPPORT, FR BUMPER RH (DISC 25%)	BROKEN	76.90	57.68
10	CLIPS PIECE, FRT & RR BUMPER @\$1.50 (DISC 25%)	NECESSARY	15.00	11.25
1	LINER, FR FENDER, RH (DISC 25%)	CRUMPLED	198.40	148.80
1	EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	52.90	39.68
1	UNIT, HEADLAMP, RH (DISC 10%)	SCRATCHED	2,558.90	2,303.01
1	LAMP ASSY, FOG, RH (DISC 10%)	CRACKED	910.20	819.18
1	SUPPORT, FR BUMPER LH	SERVICEABLE	82.30	-
1	GRILLE, RADIATOR	SERVICEABLE	165.00	-
2	RETAINER, FR BUMPER, LH & RH	SERVICEABLE	8.50	-
1	COVER ASSY, ENGINE	SERVICEABLE	180.10	-
1	SET COVER ASSY, ENGINE UNDER CENTER	SERVICEABLE	452.80	-
1	COVER, ENGINE UNDER CENTER	SERVICEABLE	94.50	-
1	GRILLE SUB-ASSY	SERVICEABLE	335.60	-
1	REINFORCEMENT FRONT UPPER	SERVICEABLE	691.10	-
1	ABSORBER, FR BUMPER	SERVICEABLE	70.30	-
1	EXTENSION SUB-ASSY, LH	SERVICEABLE	116.30	-
1	EXTENSION SUB-ASSY, RH	SERVICEABLE	116.30	-
1	REINFORCEMENT FRONT LOWER	SERVICEABLE	238.50	-
1	ABSORBER, FR BUMPER LOWER	SERVICEABLE	117.00	-
1	PAD, FR WHEEL RH	SERVICEABLE	57.70	-
1	WHEEL, DISC FRONT	SERVICEABLE	1,555.10	-
1	TYRE	SERVICEABLE	126.74	-
1	FENDER SUB-ASSY, FR, RH	TO REPAIR SEE LABOUR	933.10	-
			9,648.74	3,751.23
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY, FR, RH.		507.00	300.00
	SPRAY PAINT.		1,116.00	400.00

Report Ref No. NS/INC20003539/Qvf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

4,491.23

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).	NOT NECESSARY	120.00	-
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,103.00	740.00
	GRAND TOTAL		11,751.74	4,491.23
		1		

Report Ref No. NS/INC20003539/Qvf3e2

RECOMMENDED COST OF REPAIRS (CONFIRMED)

Ja

OI SUN PIN

Asst. Automotive Assessor

Report, in whole or in part, does so at his or her own risk.

1

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser