

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG20003546/ETF3E2

Date: 15/04/2020

REFERENCE

Insured/Claimant: LEE HWEE HOON, KAREN Policy No:
Date of Loss: 28/02/2020 Nature of Claim: OD Claim No: 4871425668SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMG5361J**
 Make & Model: AUDI A3, 1.4 SEDAN TFSI (AMBIENTE) (A) Engine No: CZE847105
 Reg. Date: 24/12/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V8K1010268
 Colour: White Odometer: 14250 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: S\$105,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,768.00	8,038.00	1,730.00	17.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,602.00	11,527.00	5,075.00	30.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	26,370.00	19,565.00	6,805.00	25.81
+ GST 7.00/7.00% (S\$)	1,845.90	1,369.55	476.35	25.81
Nett Amount (S\$)	28,215.90	20,934.55	7,281.35	25.81

INSPECTION

Date of Assignment: 04/03/2020
 Date Inspected: 03/03/2020 Inspected At: 281 ALEXANDRA ROAD
 Repairer : Premium Automobiles Pte Ltd
 Estimated Period of Repair: 12.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$2,792.00 NETT)

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR DOOR LH	Dented	2,375.00 FS	*2,375.00 FS	
2	1		*REAR DOOR OUTER SEAL LH	Necessary	151.00 FS	*151.00 FS	
3	1		*BONDING AGENT	Necessary	46.00 FS	*46.00 FS	
4	1		*CLEANING SOLUTION	Necessary	64.00 FS	*64.00 FS	
5	1		*REAR DOOR CATCH LH	Not Necessary	89.00 FS	*- FS	
6	1		*REAR DOOR WINDOW REGULATOR LH	* Check	234.00 FS	*- FS	
7	1		*REAR DOOR WINDOW GUIDE RAIL LH	Not Necessary	49.00 FS	*- FS	
8	1		*REAR DOOR ATTACHMENT PARTS	Necessary	121.00 FS	*121.00 FS	
9	1		*REAR FENDER LH	Dented	2,195.00 FS	*2,195.00 FS	
10	1		*REAR WHEEL HOUSING LINER LH	* Check	226.00 FS	*- FS	
11	1		*REAR QUARTER GLASS LH	Necessary	537.00 FS	*537.00 FS	
12	1		*REAR WINDSCREEN	Necessary	766.00 FS	*766.00 FS	
13	1		*REAR WINDSCREEN PRIMER	Necessary	37.00 FS	*37.00 FS	
14	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS	
15	1		*QUARTER GLASS SEALANT	Necessary	100.00 FS	*100.00 FS	
16	1		*ARYCLIX SEALER	Necessary	180.00 FS	*180.00 FS	
17	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS	
18	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS	
19	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS	
20	1		*ALUMINIUM RIM REAR LH	Cut	666.00 FS	*666.00 FS	
21	1		*WHEEL BEARING ASSEMBLY	* Check	448.00 FS	*- FS	
22	1		*SUNDRIES	* Check	600.00 FS	*- FS	
23	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	* Check	84.00 FS	*- FS	
					Total Parts (S\$)	9,768.00	8,038.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
2	TO RENEW LHS 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	350.00	350.00
4	TO DISLodge AND REINSTALL REAR WIE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
6	TO DISMANTLE LHS REAR DOOR, REAR BUMPER AND REAR LID. CUT OUT AND WELD LHS REAR FENDER. RENEW LHS REAR DOOR AND ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New	6,300.00	4,000.00
7	TO RESPRAY LHS REAR DOOR, LHS REAR FENDER, LHS SILL PANEL, DOOR ENTRANCES, DRAIN PANEL, ROOF CHANNEL AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORK	New	4,600.00	3,025.00
8	TO DISMANTLE LHS REAR SUSPENSION. INPSECT FOR DAMAGES AND RENEW IF NECESSARY (* Check)	New	1,200.00	0.00
9	TO REEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			16,602.00	11,527.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >