

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20003550/KVF3E2  
**Date:** 15/05/2020

**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30756219000	
Claimant Vehicle No :	SDG2208X	Insured Vehicle No :	YP3925G	
Date of Loss:	02/03/2020	Nature of Claim:	TP	Claim No: SNM20D201113C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SDG2208X</b>			
Make & Model:	MERCEDES-BENZ CLA180, 1.6 COUPE URBAN (R18 LED) (A)	Engine No:	27091031157429	
Reg. Date:	13/04/2017 (Man. Year: 2016)	Chassis No:	WDD1173422N454161	
Colour:	Silver	Odometer:	31404 km	
Engine Capacity:	1595 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	<b>Market Value/New Car Price</b>			

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,973.40	2,965.50	2,007.90	40.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,100.00	820.00	42.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>6,893.40</b>	<b>4,065.50</b>	<b>2,827.90</b>	<b>41.02</b>
<b>+ GST 7.00/7.00% (S\$)</b>	482.54	284.59	197.95	41.02
<b>Nett Amount (S\$)</b>	<b>7,375.94</b>	<b>4,350.09</b>	<b>3,025.85</b>	<b>41.02</b>

**INSPECTION**

Date of Assignment:	04/03/2020		
Date Inspected:	05/03/2020	Inspected At:	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Estimated Period of Repair:	4.0 days		

<b>Adjuster:</b> OI SUN PIN	<b>Manager:</b> VERON CHEN
-----------------------------	----------------------------

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

PLEASE BE INFORMED THAT TP WITHDRAW CLAIM.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,273.50 NETT)

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 14 May 2020)

**Parts:** 143 MERCEDES-BENZ CLA180 1.6 COUPE URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** LKK Auto Consultants Pte Ltd/SDG2208X/15/05/2020 09:56

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*SIDE MIRROR LOW COVER LH & RH	Scratched	130.00 FL	*130.00 FL
2	1		*SIDE MIRROR LOW COVER ARM LH	Serviceable	790.00 FL	*- FL
3	1		*SIDE MIRROR LOW COVER AMR RH	Crumpled	750.00 FL	*750.00 FL
4	1		*SIDE MIRROR COVER SIGNAL LAMP LH & RH	N/S Scratched / O/S * Check	410.00 FL	*205.00 FL
5	1		*SIDE MIRROR GLASS LH	* Check	190.00 FL	*- FL
6	1		*SIDE MIRROR GLASS RH	* Check	500.00 FL	*- FL
7	1		*FRONT DOOR RH	Dented	1,550.00 FL	*1,550.00 FL
8	1		*FRONT DOOR INGE TOP RH	* Check	105.00 FL	*- FL
9	1		*FRONT DOOR HINGE BOTTOM RH	* Check	130.00 FL	*- FL
10	1		*FRONT DOOR RUBBER @ DOOR RH	* Check	285.00 FL	*- FL
11	1		*FRONT FENDER RH	Dented	630.00 FL	*630.00 FL
12	8		*FRONT FENDER COWLING CLIPS	Necessary	56.00 FL	*30.00 FL

F=Franchise part. L=ListItemDisc.

**Sub Total (\$\$)** 5,526.00 3,295.00  
**- List Item Discount on L Items 10.00/10.00% (\$\$)** 552.60 329.50

**Total Parts (\$\$)** 4,973.40 2,965.50

LKK Auto Consultants Pte Ltd/SDG2208X/15/05/2020 09:56. Not valid without Reference section.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	40.00
2	TO CHECK AND RE-ADJUST FOR PROPER FUNCTIONING	New	80.00	0.00
3	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR / FACILITATE REPAIR	New	120.00	60.00
4	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	120.00	0.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR SPORT RIMS RHF, FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
7	TO SPRAY SIDE MIRROR COVER LH & RH, FRONT DOOR RH, FRONT FENDER RH, SPORTS RIM RHF	New	700.00	500.00
			<b>Gross Labour Cost (\$)</b>	<b>1,920.00</b>
				<b>1,100.00</b>

LKK Auto Consultants Pte Ltd/SDG2208X/15/05/2020 09:56. Not valid without Reference section.

< END OF ESTIMATES >