

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20003550/KVF3E2**Date:** 14/05/2020REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30756219000

Claimant Vehicle No : SDG2208X **Insured Vehicle No :** YP3925G

Date of Loss: 02/03/2020 Nature of Claim: TP Claim No: SNM20D201113C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDG2208X**

Make & Model: MERCEDES-BENZ CLA180, 1.6 COUPE URBAN (R18 LED) (A) Engine No: 27091031157429

Reg. Date: 13/04/2017 (Man. Year: 2016) Chassis No: WDD1173422N454161

Colour: Silver Odometer: 31404 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,973.40	2,965.50	2,007.90	40.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	1,100.00	820.00	42.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,893.40	4,065.50	2,827.90	41.02
+ GST 7.00/7.00% (S\$)	482.54	284.59	197.95	41.02
Nett Amount (S\$)	7,375.94	4,350.09	3,025.85	41.02

INSPECTION

Date of Assignment: 04/03/2020

Date Inspected: 05/03/2020 Inspected At:

Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09
AMK Autopoint
Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: OI SUN PIN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,273.50 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 14 May 2020)
Parts: 143	MERCEDES-BENZ CLA180 1.6 COUPE URBAN (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDG2208X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*SIDE MIRROR LOW COVER LH & RH	Scratched	130.00 FL	*130.00 FL
2	1		*SIDE MIRROR LOW COVER ARM LH	Serviceable	790.00 FL	*- FL
3	1		*SIDE MIRROR LOW COVER AMR RH	Crumpled	750.00 FL	*750.00 FL
4	1		*SIDE MIRROR COVER SIGNAL LAMP LH & RH	N/S Scratched / O/S * Check	410.00 FL	*205.00 FL
5	1		*SIDE MIRROR GLASS LH	* Check	190.00 FL	*- FL
6	1		*SIDE MIRROR GLASS RH	* Check	500.00 FL	*- FL
7	1		*FRONT DOOR RH	Dented	1,550.00 FL	*1,550.00 FL
8	1		*FRONT DOOR INGE TOP RH	* Check	105.00 FL	*- FL
9	1		*FRONT DOOR HINGE BOTTOM RH	* Check	130.00 FL	*- FL
10	1		*FRONT DOOR RUBBER @ DOOR RH	* Check	285.00 FL	*- FL
11	1		*FRONT FENDER RH	Dented	630.00 FL	*630.00 FL
12	8		*FRONT FENDER COWLING CLIPS	Necessary	56.00 FL	*30.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	5,526.00	3,295.00
- List Item Discount on L Items 10.00/10.00% (S\$)	552.60	329.50
Total Parts (S\$)	4,973.40	2,965.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	40.00
2	TO CHECK AND RE-ADJUST FOR PROPER FUNCTIONING	New	80.00	0.00
3	TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR / FACILITATE REPAIR	New	120.00	60.00
4	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	120.00	0.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
6	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR SPORT RIMS RHF, FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME	New	800.00	500.00
7	TO SPRAY SIDE MIRROR COVER LH & RH, FRONT DOOR RH, FRONT FENDER RH, SPORTS RIM RHF	New	700.00	500.00
			Gross Labour Cost (S\$)	1,920.00
				1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >