

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20003553/EKS3Q2

**Date:** 13/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100466503

**Claimant**  
**Vehicle No :** GBD6545K **Insured Vehicle No :** SCV1001P

Date of Loss: 29/02/2020 Nature of Claim: TP Claim No: 6004092594SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBD6545K		
Make & Model:	NISSAN NV350, 2.5 5MT 5DR EURO V (A)	Engine No:	YD25358774A
Reg. Date:	12/02/2015 (Man. Year: 2014)	Chassis No:	JN1MC2E26Z0003618
Colour:	Silver	Odometer:	189334 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,499.21	3,080.43	3,418.78	52.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,110.00	1,400.00	710.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>8,609.21</b>	<b>4,480.43</b>	<b>4,128.78</b>	<b>47.96</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>8,609.21</b>	<b>3,600.00</b>	<b>5,009.21</b>	<b>58.18</b>
<b>+ Loss of Use (7.0 x S\$90.00/day) (S\$)</b>		630.00		
<b>Nett Liability (S\$)</b>		<b>4,230.00</b>		

### INSPECTION

Date of Assignment: 03/03/2020

Date Inspected: 04/03/2020 Inspected At:

Car Pro Auto (HQ)  
Blk 6 Yew Tee Industrial Estate 399-J,  
Woodlands Road  
Singapore 678008

Estimated Period of Repair: 6.0 days

**Adjuster:** CHEN TSUE YEE

**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER (W/STEP GARNISH)	Deformed	680.00 FL	*680.00 FL
2	1		*REAR BUMPER (INNER) CENTRE BRACKET	Not Necessary	208.90 FL	*- FL
3	1		*REAR RIGHT FENDER	Dented	2,010.00 FL	*2,010.00 FL
4	1		*TAILGATE	Not Necessary	1,842.00 FL	*- FL
5	1		*SET TAILGATE GARNISH FASTENERS	Not Necessary	36.00 FL	*- FL
6	1		*SET REAR RIGHT ABSORBER	Not Necessary	180.00 FL	*- FL
7	1		*REAR RIGHT TYRE RIM OUTER COVER	Broken	110.00 FL	*110.00 FL
8	1		*REAR RIGHT WHEEL HUB	Not Necessary	498.00 FL	*- FL
9	1		*REAR RIGHT WHEEL BEARING	Jammed	380.00 FL	*108.70 FL
10	1		*TAILGATE NISSAN EMBLEM	Not Necessary	70.00 FL	*- FL
11	1		*TAILGATE NV 350 EMBLEM	Not Necessary	70.00 FL	*- FL
12	1		*TAILGATE URVAN EMBLEM	Not Necessary	70.00 FL	*- FL
13	1		*TAILGATE WEATHERSTRIP	Not Necessary	140.00 FL	*- FL
14	2		*REAR BUMPER SIDE RETAINER	Broken	54.00 FL	*54.00 FL
15	1		*TAILLAMP (W/GASKET) (RH)	Cut	260.00 FL	*260.00 FL
16	1		*TAILLAMP FASTENERS	Not Necessary	18.00 FL	*- FL
17	1		*SET REVERSE SENSOR	Not Necessary	250.00 FS	*- FS
18	1		*REAR 70KM/H STICKER	Not Necessary	35.00 FS	*- FS
19	1		*REAR RIGHT TYRE RIM	Twisted	250.00 FS	*180.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>7,161.90</b>	<b>3,402.70</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	662.69	322.27

<b>Total Parts (\$\$)</b>	<b>6,499.21</b>	<b>3,080.43</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	600.00	600.00
2	TO CHECK WIRING AND REWIRE	New	50.00	30.00
3	TO REMOVE AND REINSTALL REAR RIGHT UNDERCARRIAGE ITEM	New	120.00	80.00
4	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	120.00	80.00
5	TO REMOVE AND REINSTALL REVERSE SENSOR	New	140.00	30.00
6	TO REMOVE AND REINSTALL FUEL TANK	New	180.00	50.00
7	TO REMOVE AND REINSTALL REAR EXHAUST MUFFLER	New	120.00	0.00
8	TO ANTI-RUST	New	180.00	30.00
9	TO PUTTY AND SPRAY PAINT OF AFFECTED AREAS	New	600.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,110.00</b>	<b>1,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >