

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

INV Date Reference 06/10/2020 CC6/FCI20003554/Uda3q2

Code

AC2006866

PROFESSIONAL SERVICE FEE

Vehicle No. FW 180X

Insured Veh. SHD 4440X

Claim No. D20001220MFSH/1

Policy No. D-18088936MFSH

Accident Date 24/02/2020

Inspection Date 04/03/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile				
MS F	S FIRST CAPITAL INSURANCE LTD Ref: CC6/FCl20003554/Uda3q2				
	36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 06-10-2020 Code: FCI2		
1.		Policy Particulars	:- THIRD PARTY CLAIM		
	Insured Veh.	SHD 4440X	Veh. Inspected	FW 180X	
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
	Claim No.	D20001220MFSH/1	Excess (\$)	0.00	
	Assign From	VIC	Assign Date	04/03/2020	
2.		Vehicle Partic	culars & Condition		
	Make & Model	HONDA FJS400A	c.c	399	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JH2NF039X9K000241	Colour	GREY	
	Odometer	45299	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.		Condition	ons of Tyres		
		Size	Make	Balance	
	R/H Front Tyre	120/80-14	DUNLOP	6 mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre	150/70-13	MICHELIN	6 mm	
	L/H Rear Tyre			mm	
4.		•	on of Damages		
	THE VEHICLE SUS	STAINED DAMAGES AT THE N/S	REAR PORTION AND N/S E	BODY.	
	DAMAGES SEE DI	ETAILS.			
5.		General	Information		
	Accident Date	24/02/2020	Inspection Date	04/03/2020	
	Survey held at	at EROFIA MOTOR TRADING PTE LTD			
		1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883			
5a.		Re	emarks		
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	4 Working Days		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 180X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
2	FORK INNER TUBES	NOT NECESSARY	570.00	-
2	FORK OUTER TUBES	NOT NECESSARY	590.00	-
1	FRONT RIM SHAFT	NOT NECESSARY	38.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	150.00	-
1	FRONT SPORT RIM	NOT NECESSARY	450.00	-
1	FRONT SIGNAL	CRACKED	120.00	115.00
1	HEADLAMP	CRACKED	320.00	320.00
1	SIDE MIRROR-L/H	CUT	85.00	85.00
1	HANDLE BAR	NOT NECESSARY	150.00	-
1	HANDLE BAR END	NOT NECESSARY	45.00	-
1	BRAKE LEVER	SCRATCHED	32.00	32.00
1	FOOTSTEP PANEL	CUT	145.00	145.00
1	MAINSTAND	DEEP CUT	185.00	185.00
1	TRANSMISSION OUTER COVER	CUT	350.00	350.00
1	SET FAIRING COVER	CRACKED	1,150.00	1,080.00
	LESS 10% DISCOUNT		-438.00	-231.20
			3,942.00	2,080.80
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN)	NOT NECESSARY	28.00	-
2	FORK OILS (SN)	NOT NECESSARY	30.00	-
2	FORK OIL SEALS (SN)	NOT NECESSARY	56.00	-
1	SET STEERING CONE (SN)	NOT NECESSARY	120.00	-
1	REAR BOX (SN)	CUT	650.00	400.00
1	REAR BOX BRACKET (SN)	NOT NECESSARY	150.00	-
			1,034.00	400.00
	<u>LABOUR</u>			
	TO PROVIDE TOWING SERVICE.	NOT NECESSARY	45.00	-
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR.		480.00	300.00

Report Ref No. CC6/FCI20003554/Uda3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO RESPRAY PAINTING.		600.00	500.00
			1,205.00	800.00
	GRAND TOTAL		6,181.00	3,280.80

RECOMMENDED COST OF LUMP SUM REPAIRS		2,600.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC6/FCI20003554/Uda3q2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R


PHOTOGRAPHS FOR VEHICLE NO. FW 180X



















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3591 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No: 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FW 180X


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FW 180X

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315



