



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2007607
INV Date 12/11/2020
Reference CC4/LPC20003559/T1ka3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. GBD 2836Y
Insured Veh. YM 6881U
Claim No. 19/20/20/VC06/023137
Policy No. Z/19/VC06/104971
Accident Date 26/02/2020
Inspection Date 04/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20003559/T1ka3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 12-11-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YM 6881U	Veh. Inspected	GBD 2836Y
Policy No.	Z/19/VC06/104971	Coverage (\$)	0.00
Claim No.	19/20/20/VC06/023137	Excess (\$)	0.00
Assign From	GERALD	Assign Date	04/03/2020

2. Vehicle Particulars & Condition

Make & Model	SSANGYONG ACTYON SPORTS D/CAB	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KPADA1ETSEP198162	Colour	WHITE
Odometer	83793	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/75 R16	FIRENZA	6 mm
L/H Front Tyre	225/75 R16	FIRENZA	6 mm
R/H Rear Tyre	225/75 R16	FIRENZA	6 mm
L/H Rear Tyre	225/75 R16	FIRENZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/02/2020	Inspection Date	04/03/2020
Survey held at	MOTORWAY CAR CARE CENTRE PTE LTD 1094 LOWER DELTA ROAD MOTORWAY BUILDING . SINGAPORE 169205		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2836Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,150.00	1,150.00
1	FRONT BUMPER RETAINER RH	NECESSARY	89.00	89.00
1	FRONT HEADLAMP RH	CRACKED	1,500.00	1,500.00
1	FRONT FENDER RH	BENT	580.00	580.00
1	FRONT FENDER UNDER-DUST COVER RH	NOT NECESSARY	190.00	-
1	FRONT FOGLAMP RH	NOT NECESSARY	250.00	-
	LESS 10% DISCOUNT		-375.90	-331.90
			3,383.10	2,987.10
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	40.00	30.00
1	FRONT FENDER UNDER-DUST COVER CLIPS (SN)	NOT NECESSARY	40.00	-
			80.00	30.00
	<u>LABOUR</u>			
	TOWING.	NOT NECESSARY	60.00	-
	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT,CUT/WELD,STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.		1,200.00	600.00
	TO PUTTY & SPRAY PAINTING ON FRONT AFFECTED AREAS.		1,350.00	900.00
	TO REMOVE,REARRANGE ELECTRICAL WIRING,CHECK LIGHTING & RESET HEADLAMP FOCUSING.		180.00	60.00
	TO APPLY RUSTPROOFING/TUFFCOATING TREATMENT TO REPLACED PARTS.		180.00	60.00
	TO CARRY OUT DIAGNOSTIC TEST.		400.00	250.00
	COMPUTERIZED ALIGNMENT.	NOT NECESSARY	180.00	-
			-	-
			-	-
			-	-
			3,550.00	1,870.00
	GRAND TOTAL		7,013.10	4,887.10



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,900.00
-------------------------------------------------------------------------	--	--	----------

Report Ref No. CC4/LPC20003559/T1ka3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBD 2836Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBD 2836Y

RE-INSPECTION

