5/18/2021 Adjuster Report

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20003564/KBS3Q2

Date:

18/05/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Nature of Claim:

2100500155

Claimant Vehicle No:

SHC5831A 29/02/2020 Insured Vehicle No:

SLK9813L TP

Claim No:

3107859561SG

M9R8839C002777

589851 km

VF1ABL15AUC281402

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHC5831A

Make & Model: RENAULT LATITUDE, 2.0 L (A) 06/03/2015 (Man. Year: 2015) Reg. Date:

Colour: Metallic White/Red

**Engine Capacity:** 1995 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

**Engine Modification:** Yes

No

Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 215/60 R16 Front Left Side: Sailun 9 mm Front Right Side: Sailun 9 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 215/60 R16 Sailun 8 mm Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		43,364.70	5,538.56	37,826.14	87.23
Miscellaneous Items		0.00	0.00	0.00	
Labour		19,620.00	1,910.00	17,710.00	90.27
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	62,984.70	7,448.56	55,536.14	88.17
	Approved Total (Overridden) (S\$)		5,950.00		

(C¢)	62,984.70	5,950.00	57,034.70	90.55
(S\$)	02,964.70	5,950.00	57,034.70	90.55
+ GST 7.00/7.00% (S\$)	4,408.93	416.50	3,992.43	90.55
Nett Amount (S\$)	67,393.63	6,366.50	61,027.13	90.55
+ Car Rental (8.0	c S\$81.13/day) (S\$)	649.04		
+ Doc/Search Fee (S\$)		7.45		
	Nett Liability (S\$)	7,022.99		
Global Si	ım Settlement (S\$)	7.000.00		

**INSPECTION** 

Date of Assignment: 03/03/2020

TRANS-CAB AUTO SERVICES PTE LTD Date Inspected: Inspected At: NO.2 ANG MO KIO ST 63 03/03/2020

SINGAPORE 569111

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly

# **REPAIR DETAILS**

## **Recommended Parts**

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*DOOR PANEL FRT LH	Repair	2,844.66 FL	*- FL
2 1	*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
3 1	*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
4 1	*DOOR CHECK FRT LH	Serviceable	90.90 FL	*- FL
5 1	*DOOR REGULATOR FRT LH	Serviceable	758.10 FL	*- FL
6 1	*DOOR REGULATOR MOTOR FRT LH	Serviceable	501.40 FL	*- FL
7 1	*DOOR REGULATOR GUIDE FRT LH	Serviceable	69.00 FL	*- FL
3 1	*DOOR WEATHERSTRIP FRT LH	Serviceable	316.00 FL	*- FL
9 1	*DOOR SEAL FRONT LH	Serviceable	69.60 FL	*- FL
10 1	*DOOR SEAL FRONT LH	Serviceable	63.10 FL	*- FL
11 1	*DOOR SEAL LOWER FRT LH	Serviceable	93.90 FL	*- FL
12 1	*DOOR MOULDING BLACK FRT LH	Serviceable	100.50 FL	*- FL
13 1	*DOOR FINISHER FRT LH	Serviceable	258.90 FL	*- FL
14 1	*DOOR FINISHE CLIP KIT FRT LH	Not Necessary	94.00 FL	*- FL
15 1	*DOOR FINISHER INNER FRT LH	Serviceable	197.10 FL	*- FL
16 1	*DOOR GLASS RUBBER SEAL FRONT LH	Serviceable	332.00 FL	*- FL
17 1	*DOOR HANDLE OUTER FRONT LH	Serviceable	169.50 FL	*- FL
18 1	*DOOR HANDLE CAP FRONT LH	Serviceable	17.30 FL	*- FL
19 1	*DOOR HANDLE MODULE FRT LH L70Y	Serviceable	133.40 FL	*- FL
20 1	*DOOR LOCK FRT LH	Repair	453.80 FL	*- FL
21 1	*DOOR WAIST SEAL OUTER FRT LH	Serviceable	92.20 FL	*- FL
22 1	*DOOR MIRROR ASSY LH	Serviceable	727.90 FL	*- FL
23 1	*DOOR MIRROR LAMP LH	Serviceable	134.10 FL	*- FL
24 1	*DOOR HARNESS WIRE LH	Serviceable	2,670.00 FL	*- FL
25 1	*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
26 1	*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
27 1	*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	*- FL
28 1	*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
29 1	*FENDER PANEL FRT LH	Bent	414.40 FL	*414.40 FL
30 1	*WHEELARCH FRT LH	Torn	112.30 FL	*112.30 FL
31 1	*FENDER BRACKET LOWER LH	Missing	11.80 FL	*11.80 FL
32 1	*FENDER INSULATOR LH	Serviceable	65.50 FL	*- FL
33 1	*FENDER BRACKER FRT LH	Repair	38.90 FL	*- FL
34 1	*FENDER PANEL INNER FRT LH	Repair	858.30 FL	*- FL
35 1	*BUMPER COVER FRT	Cracked	747.20 FL	*747.20 FL

lo. Qty Part No.	Particulars Condition		Repairer's	Amount
6 1	*BUMPER RETAINER FRT LH	Cracked	101.40 FL	*101.40 FL
7 1	*BUMPER SPOILER FRT	Distorted	344.70 FL	*344.70 FL
8 1	*BUMPER ABSORBER FRT	Cracked	394.68 FL	*394.68 FL
9 1	*BUMPER SUPPORT GTY	Serviceable	10.70 FL	*- FL
0 1	*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*- FL
1 1	*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*- FL
2 1	*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*- FL
3 1	*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
4 1	*HEADLAMP LH	Mtg Broken	743.60 FL	*743.60 FL
5 1	*HEADLAMP PANEL FRT LH	Repair	127.70 FL	*- FL
6 1	*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
7 1	*RADIATOR GRILLE	Serviceable	969.90 FL	*- FL
8 1	*RADIATOR GRILLE BADGE RENAULT	Serviceable	225.36 FL	*- FL
9 1	*RADIATOR GRILLE FRAME	Serviceable	686.00 FL	*- FL
0 1	*FRAME FULL SUPPORT PANEL	Serviceable	592.70 FL	*- FL
1 1	*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*- FL
2 1	*BONNET	Bent	1,312.70 FL	*1,312.70 FL
3 1	*BONNET INSULATOR	Serviceable	294.30 FL	*- FL
4 1	*BONNET STRUT LH	Serviceable	53.30 FL	*- FL
5 1	*BONNET HINGE LH	Repair	236.50 FL	*- FL
6 1	*BONNET LOCK	Repair	152.80 FL	*- FL
7 1	*SUBFRAME OUTER FRNT	Serviceable	1,094.20 FL	*- FL
8 1	*SUBFRAME BRACKET OUTER LH	Serviceable	49.00 FL	*- FL
9 1	*DOOR PANEL REAR LH	Repair	758.70 FL	*- FL
0 1	*DOOR GUIDE REAR LH	Serviceable	136.40 FL	*- FL
1 1	*DOOR HINGE UPPER REAR LH L70Y	Repair	180.70 FL	*- FL
2 1	*DOOR HINGE LOWER REAR LH L70Y	Repair	169.90 FL	*- FL
3 1	*DOOR CHECK REAR LH	Serviceable	114.90 FL	*- FL
4 1	*DOOR REGULATOR REAR LH L70Y	Serviceable	657.10 FL	*- FL
5 1	*DOOR REGULATOR MOTOR REAR LH L70Y	Serviceable	450.60 FL	*- FL
6 1	*DOOR HANDLE OUTER REAR LHL70Y	Serviceable	42.10 FL	*- FL
7 1	*DOOR HANDLE CAP REAR LH L70Y	Serviceable	57.90 FL	*- FL
8 1	*DOOR HANDLE MODULE REAR LH L70Y	Serviceable	133.40 FL	*- FL
9 1	*DOOR SEAL REAR LH	Serviceable	119.40 FL	*- FL
0 1	*DOOR WEATHERSTRIP REAR LH	Serviceable	240.50 FL	*- FL
1 1	*DOOR LOCK REAR LH L70Y	Repair	468.20 FL	*- FL
2 1	*FENDER PANEL REAR LH	Repair	1,933.20 FL	*- FL
	*FENDER PANEL INNER TRIM REAR LH	Repair	671.45 FL	*- FL
4 1	*WHEELARCH REAR LH	Serviceable	181.60 FL	*- FL
· · · · · · · · · · · · · · · · · · ·	*AIR CLEANER BOX	Serviceable	464.20 FL	*- FL

Report was unsubmitted during this print-out.

No. Qty Part No.	Particulars Condition		Repairer's	Amount
<b>7</b> 6 1	*AIR CLEANER HOSE	Serviceable	175.85 FL	*- FL
77 1	*AIR CLEANER LOWER	Cracked	271.26 FL	*271.26 FL
78 1	*LOWER ARM LH L70Y	Serviceable	192.70 FL	*- FL
79 1	*KNUCKLE ARM LH L70Y	Bent	481.50 FL	*481.50 FL
30 2	*KNUCKLE HUB +BEARING LH/RH	Necessary	272.30 FL	*272.30 FL
31 1	*ABSORBER FRT LH L70Y	Serviceable	274.10 FL	*- FL
32 1	*ABSORBER MOUNTING KIT	Serviceable	273.60 FL	*- FL
33 1	*ABSORBER DUST COVER	Serviceable	52.40 FL	*- FL
34 1	*DRIVESHAFT LH	Serviceable	1,355.70 FL	*- FL
35 1	*FRT STABILIZER BAR	Serviceable	427.90 FL	*- FL
36 1	*STABILIZER LINK FRT	Serviceable	69.50 FL	*- FL
37 1	*INJECTION COMPUTER	Serviceable	2,706.30 FL	*- FL
38 1	*AUTO COMPUTER	Serviceable	1,287.30 FL	*- FL
39 1	*STEERING PUMP ELECTRIC	Serviceable	2,026.70 FL	*- FL
90 1	*STEERING PINION RACK	Serviceable	3,765.30 FL	*- FL
91 1	*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
92 1	*FRONT DOOR STICKER CLASSIC	Necessary	80.00 FS	*15.00 FS
93 1	*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
94 1	*LH SIDE RENAULT TYRE 215/60/16 (80%)	Punctured	300.00 FS	*240.00 FS
95 1	*LH SIDE RENAULT TYRE RIM	Dented	380.00 FS	*380.00 FS
96 1	*LH SIDE RENAULT TYRE RIM COVER	Serviceable	60.00 FS	*-FS
97 1	*WHEELARCH CLIP FRT LH	Necessary	30.50 FS	*30.50 FS
98 1	*FRONT WINDSCREEN MOULDING	Not Necessary	160.00 FS	*-FS
9 2	*WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
100 1	*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
101 1	*DOOR CHECK BOLT	Serviceable	10.20 FS	*- FS
102 1	*DOOR CHECK NUT	Serviceable	10.20 FS	*- FS
103 1	*DOOR GUIDE SCREW	Serviceable	10.85 FS	*- FS
104 1	*DOOR HINGE BOLT	Serviceable	10.85 FS	*- FS
105 1	*DOOR HINGE NUT LH	Serviceable	7.20 FS	*- FS
106 1	*DOOR LOCK SCREW L70Y	Serviceable	3.60 FS	*- FS
107 1	*DOOR SEAL CLIP LH	Not Necessary	4.90 FS	*- FS
108 1	*BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
109 1	*BUMPER BRACKET CLIP FRT LH	Not Necessary	12.00 FS	*- FS
110 1	*BUMPER SUPPORT CLIP FRT LH	Not Necessary	10.50 FS	*- FS
111 1	*BUMPER GILLE LOWER CLIP	Not Necessary	69.00 FS	*- FS
112 1	*FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
113 1	*SET FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
114 2	*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*- FS
115 1	*SET RADIATOR GRILLE SCREW	Not Necessary	16.00 FS	*-FS

Report was unsubmitted during this print-out.

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
116 1	*SET RADIATOR GRILLE FRAME CLIP	Not Necessary	52.00 FS	*-FS
117 1	*SET FRONT LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*-FS
118 1	*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*-FS
119 1	*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
F=Franchise part. S=SpcNett. L=	=ListItemDisc.			
		Sub Total (S\$)	47,965.58	6,059.34
		- List Item Discount on L Items 10.00/10.00% (S\$)	4,600.88	520.78
		Total Parts (S\$)	43,364.70	5,538.56
	Poport was	Total Parts (	S\$)	<b>S\$)</b> 43,364.70

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	7,500.00	600.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
4	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH TO FACILITATE REPAIR	New	380.00	0.00
5	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	1,100.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	20.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
9	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
10	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
11	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
12	TOWING FEES	New	150.00	50.00
13	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
14	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
15	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
16	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
17	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
18	TO TRANSFER OF FRONT BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
19	TO DISMANTLE AND REFIT ENGINE CROSS -MEMBER AND ENGINE MOUNTING	New	380.00	0.00
20	TO REMOVE AND RENEW POWER STEERING PUMP ,OIL COOLER PIPE AND FINAL CHECKING AND TESTING	New	440.00	0.00
	Gross Labo	our Cost (S\$)	19,620.00	1,910.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >