

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 1698A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE (CONSISTENT)	TO REPAIR SEE LABOUR	1,521.50	-
1	TAILGATE EMBLEM 'HARRIER' (CONSISTENT)	NECESSARY	95.40	81.00
1	REAR SMART KEYLESS SENSOR (CONSISTENT)	BROKEN	230.50	230.50
1	REAR BUMPER (CONSISTENT)	CUT	1,375.30	1,343.12
1	REAR BUMPER LOWER (CONSISTENT)	BROKEN	401.60	401.60
2	REAR BUMPER SIDE RETAINER @\$170.00 (CONSISTENT)	NECESSARY	340.00	205.80
2	REAR BUMPER BRACKET @\$68.50 (CONSISTENT)	NOT NECESSARY	137.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	715.00	-
1	REAR BUMPER SPONGE (CONSISTENT)	BROKEN	127.80	127.80
	LESS 25% DISCOUNT		-1,236.03	-597.46
			3,708.07	1,792.36
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
2	REAR BUMPER REVERSE SENSOR @\$200.00 (SN) (CONSISTENT)	NOT DAMAGED	400.00	-
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	TAILGATE SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	100.00	-
			730.00	30.00
	LABOUR			
	R & R TAILGATE COMPONENT.	NOT NECESSARY	100.00	-
	PANEL BEAT.INCLUSIVE OF THE REPAIR OF TAILGATE.		800.00	200.00
	RUST PROOFING .	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		800.00	400.00
	CHECK WIRING .		80.00	30.00
			1,980.00	630.00
	GRAND TOTAL		6,418.07	2,452.36

Report Ref No. CC4/ASM20003566/Bpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,950.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM20003566/Bpa3q2

LIM TEOW GUAN

**Automotive Assessor** 

**HO LEONG CHUAN** 

**Automotive Assessor**