

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20003569/R1GS3Q2

**Date:** 27/07/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SJS8319K	<b>Insured Vehicle No :</b>	SH8505R
Date of Loss: 29/02/2020	Nature of Claim: TP	Claim No: MCT20020603

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS8319K	Engine No:	3ZZ4931033
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEE106154758
Reg. Date:	09/09/2009 (Man. Year: 2009)	Odometer:	165656 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,884.84	5,384.37	3,500.47	39.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,690.00	2,000.00	690.00	25.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>11,574.84</b>	<b>7,384.37</b>	<b>4,190.47</b>	<b>36.20</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,900.00</b>		
<b>(\$\$)</b>	11,574.84	5,900.00	5,674.84	49.03
<b>+ GST 7.00/7.00% (\$\$)</b>	810.24	413.00	397.24	49.03
<b>Nett Amount (\$\$)</b>	<b>12,385.08</b>	<b>6,313.00</b>	<b>6,072.08</b>	<b>49.03</b>
<b>+ Car Rental (8.0 x S\$107.00/day) (\$\$)</b>		856.00		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>7,176.45</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>7,000.00</b>		

### INSPECTION

Date of Assignment:	04/03/2020	
Date Inspected:	04/03/2020 Inspected At:	1 KAKI BKT AVE 6 # 02-26
		Repairer: Carz Auto Services Pte Ltd (HQ)
Estimated Period of Repair:	7.0 days	

---

**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Apr 2020)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJS8319K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT LEFT FENDER	Repair	684.20 FL	*- FL
2	1	*FRONT LEFT FENDER VVTI EMBLEM	Necessary	66.70 FL	*66.70 FL
3	1	*FRONT LEFT DOOR	Bent	1,170.40 FL	*1,170.40 FL
4	1	*FRONT LEFT DOOR LOCK	Serviceable	599.50 FL	*- FL
5	2	*FRONT LEFT DOOR HINGE	Serviceable	154.10 FL	*- FL
6	1	*FRONT LEFT DOOR WEATHERSTRIP	Necessary	109.25 FL	*109.25 FL
7	1	*FRONT LEFT INNER DOOR WEATHERSTRIP	Serviceable	111.55 FL	*- FL
8	1	*FRONT LEFT DOOR PROTECTOR GARNISH	Deformed	109.25 FL	*109.25 FL
9	1	*FRONT LEFT DOOR CHECK	Serviceable	146.05 FL	*- FL
10	1	*FRONT LEFT DOOR SIDE STEP COVER GARNISH	Serviceable	129.95 FL	*- FL
11	1	*FRONT LEFT DOOR POWER WINDOW MOTOR	Shorted	621.50 FL	*621.50 FL
12	1	*FRONT LEFT DOOR POWER WINDOW REGULATOR	Bent	249.55 FL	*249.55 FL
13	1	*FRONT LEFT DOOR POWER WINDOW CHANNEL	Serviceable	155.25 FL	*- FL
14	1	*FRONT LEFT DOOR GLASS MOULDING	Necessary	97.75 FL	*97.75 FL
15	1	*FRONT LEFT DOOR INNER TRIM BOARD	Deformed	1,072.50 FL	*1,072.50 FL
16	1	*FRONT LEFT CENTRE PILLAR	Bent	412.50 FL	*412.50 FL
17	1	*FRONT LEFT ROCHER PANEL	Repair	621.50 FL	*- FL
18	1	*FRONT LEFT SIDE SKIRT	Scratched	599.50 FL	*599.50 FL
19	1	*REAR LEFT DOOR	Bent	1,072.50 FL	*1,072.50 FL
20	1	*REAR LEFT DOOR LOCK	Serviceable	632.50 FL	*- FL
21	1	*REAR LEFT DOOR HINGES	Bent (Bottom)	154.10 FL	*77.05 FL
22	1	*REAR LEFT DOOR CHECK	Serviceable	146.05 FL	*- FL
23	1	*REAR LEFT DOOR WEATHERSTRIP	Necessary	120.75 FL	*120.75 FL
24	1	*REAR LEFT DOOR GLASS MOULDING	Necessary	111.55 FL	*111.55 FL
25	1	*REAR LEFT DOOR PROTECTOR GARNISH	Deformed	109.25 FL	*109.25 FL
26	1	*REAR LEFT DOOR SIDE STEP COVER GARNISH	Serviceable	129.95 FL	*- FL
27	1	*REAR LEFT DOOR INNER TRIM BOARD	Deformed	1,072.50 FL	*1,072.50 FL
28	1	*REAR LEFT DOOR POWER WINDOW MOTOR	Serviceable	621.50 FL	*- FL
29	1	*REAR LEFT DOOR WINDOW CHANNEL	Serviceable	155.25 FL	*- FL
30	1	*REAR LEFT DOOR POWER WINDOW REGULATOR	Serviceable	249.55 FL	*- FL
31	1	*FRONT LEFT DOOR INNER TRIM BOARD CLIPS (12 PCS)	Necessary	60.00 FS	*40.00 FS
32	1	*REAR LEFT DOOR INNER TRIM BOARD CLIPS (12 PCS)	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>11,806.45</b>	<b>7,152.50</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	2,921.61	1,768.13
<b>Total Parts (\$\$)</b>	<b>8,884.84</b>	<b>5,384.37</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND RENEW DAMAGED PARTS REPLACE REALIGNED ALL AFFECTED PARTS	New	1,200.00	800.00
2	TO RESPRAY AFFECTED AREAS	New	1,000.00	900.00
3	TO TUFFCOAT AFFECTED AREA	New	150.00	80.00
4	TO REMOVE/REFIX INTERIOR UPHOLSTERY	New	100.00	60.00
5	TO REMOVE/REFIX WIRING CHECKS	New	60.00	40.00
6	TO REMOVE/REPLACE DOOR MECHANISM	New	100.00	60.00
7	TO COMPUTERISED FOUR WHEEL ALIGNMENT	New	80.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>2,690.00</b>	<b>2,000.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**