

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/FWD20003584/UGA3Q2

**Date:** 08/09/2020

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00010473-01

**Claimant**  
**Vehicle No :** SGD6683K **Insured Vehicle No :** SJD8161B

**Date of Loss:** 04/03/2020 **Nature of Claim:** TP **Claim No:** 1202000011451

### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	<b>SGD6683K</b>	<b>Engine No:</b>	4A910020445
<b>Make &amp; Model:</b>	MITSUBISHI COLT PLUS, 1.5 (A)	<b>Chassis No:</b>	JMYLTZ23W6Z000288
<b>Reg. Date:</b>	21/02/2006 (Man. Year: 2006)	<b>Odometer:</b>	145390 km
<b>Colour:</b>	White		
<b>Engine Capacity:</b>	1499 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R14	Rear Tyre Size:	185/60 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,244.00	1,787.20	2,456.80	57.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,580.00	1,300.00	45.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,124.00</b>	<b>3,367.20</b>	<b>3,756.80</b>	<b>52.73</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>2,600.00</b>		
<b>(\$\$)</b>	7,124.00	2,600.00	4,524.00	63.50
<b>+ GST 7.00/7.00% (\$\$)</b>	498.68	182.00	316.68	63.50
<b>Nett Amount (\$\$)</b>	<b>7,622.68</b>	<b>2,782.00</b>	<b>4,840.68</b>	<b>63.50</b>
<b>+ Car Rental (5.0 x S\$100.00/day) (\$\$)</b>		500.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>3,284.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>3,250.00</b>		

### INSPECTION

**Date of Assignment:** 04/03/2020

**Date Inspected:** 04/03/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883

**Estimated Period of Repair:** 4.0 days

---

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)
<b>Parts:</b>	144	MITSUBISHI COLT PLUS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGD6683K)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	118.00 F	*- FL
2	1		*TAILGATE	Repair	981.00 F	*- FL
3	1		*TAILGATE REAR LOGO	Necessary	45.00 F	*45.00 FL
4	1		*TAILGATE COLT EMBLEM	Necessary	48.00 F	*48.00 FL
5	1		*TAILGATE PLUS EMBLEM	Necessary	42.00 F	*42.00 FL
6	1		*TAILGATE C&C LOGO	Necessary	45.00 F	*45.00 FL
7	1		*TAILGATE WEATHERSTRIP	Twisted	191.00 F	*191.00 FL
8	1		*TAILGATE INNER LOCK	Not Necessary	166.00 F	*- FL
9	1		*REAR BUMPER	Dented / Deformed	745.00 F	*692.00 FL
10	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	90.00 F	*- FL
11	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
12	1		*REAR BUMPER REFLECTOR N/S	Cracked	68.00 F	*38.00 FL
13	1		*REAR END PANEL	Dented / Bent	605.00 F	*445.00 FL
14	1		*REAR END PANEL TOP GARNISH	Twisted	185.00 F	*112.00 FL
15	1		*TAILLAMP N/S	Not Necessary	485.00 F	*- FL
16	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
17	1		*SET REAR BUMPER REVERSE SENSOR	Shorted / Torn	280.00 FS	*200.00 FS
18	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,244.00</b>	<b>1,958.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	170.80
<b>Total Parts (\$\$)</b>	<b>4,244.00</b>	<b>1,787.20</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO SPRAY RUST PROOFING	New	100.00	30.00
6	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	880.00	600.00
7	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,880.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >