

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003585/ABA3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900003962
Claimant
Vehicle No : SLZ1071J **Insured Vehicle No :** SJQ8138B
 Date of Loss: 04/03/2020 Nature of Claim: TP Claim No: 1986419358SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLZ1071J**
 Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZ905062
 Reg. Date: 23/04/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V2J1056287
 Colour: Grey Odometer: 29654 km
 Engine Capacity: 999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,967.00	3,566.80	1,400.20	28.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,652.00	2,102.00	1,550.00	42.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,619.00	5,668.80	2,950.20	34.23
+ GST 7.00/7.00% (S\$)	603.33	396.82	206.51	34.23
Nett Amount (S\$)	9,222.33	6,065.62	3,156.71	34.23
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
		6,245.62		
		Nett Liability (S\$)		

INSPECTION

Date of Assignment: 12/03/2020
 Date Inspected: 12/03/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)
 55 UBI ROAD 1
 Singapore 408699
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*RADIATOR GRILLE	Cracked	1,338.00 FS	*1,070.40 FS	
2	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	180.00 FS	*- FS	
3	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS	
4	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS	
5	1		*BONNET	Dented	2,988.00 FS	*2,390.40 FS	
6	1		*BONNET ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS	
7	1		*BONNET EDGE PROTECTION	Not Necessary	26.00 FS	*- FS	
8	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS	
9	1		*SUNDRIES	Necessary	200.00 FS	*30.40 FS	
					Total Parts (S\$)	4,967.00	3,566.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE FRONT BUMPER AND BONNET .TO RENEW BONNET .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,000.00
3	TO RESPRAY BONNET	New	1,000.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,652.00	2,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >