

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20003587/EEA3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800088914

Claimant
Vehicle No : SMP8654Y **Insured Vehicle No :** SFY886H

Date of Loss: 27/02/2020 Nature of Claim: TP Claim No: 3462900915SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP8654Y		
Make & Model:	BMW X2, 2.0 SDrive20i (A)	Engine No:	H4013313B48B20A
Reg. Date:	18/10/2019 (Man. Year: 2019)	Chassis No:	WBATR12030LS31265
Colour:	Black	Odometer:	7407 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,528.50	1,978.55	1,549.95	43.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,545.00	5,019.00	2,526.00	33.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,073.50	6,997.55	4,075.95	36.81
+ GST 7.00/7.00% (\$\$)	775.15	489.83	285.32	36.81
Nett Amount (\$\$)	11,848.65	7,487.38	4,361.27	36.81
+ Loss of Use (6.0 x S\$100.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		8,089.38		

INSPECTION

Date of Assignment: 23/03/2020

Date Inspected: 23/03/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*DISK WHEEL	Cut	1,457.45 FS	*1,603.20 FS
3	1		*RH BUMPER GUIDE	Not Necessary	70.30 FS	*- FS
4	1		*REAR BUMPER PANEL PRIMED (M/PMA)	Repair	1,555.40 FS	*- FS
5	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
6	1		*RR RH WHEEL ARCH TRIM PRIMED (M)	Cut	281.35 FS	*281.35 FS
					Total Parts (S\$)	3,528.50 1,978.55

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,REAR RIGHT WHEEL ARCH TRIM AND REPAIR REAR RIGHT FENDER	New	3,400.00	2,125.00
2	PAINTING REAR RIGHT FENDER ,REAR BUMPER AND REAR RIGHT WHEEL ARCH TRIM	New	2,293.00	2,063.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE AND INSTALL REAR HAT-TRAY ,REAR SEAT ,CARPET AND ROOF TOP LINING TO FACILITATE REPAIRS	New	873.00	0.00
5	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
6	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING	New	94.00	80.00
7	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION	New	531.00	451.00
Gross Labour Cost (\$\$)			7,545.00	5,019.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >