



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005623
INV Date 17/08/2020
Reference CC6/FCI20003595/Uda3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKN 628K
Insured Veh. SHC 3680G
Claim No. D20/1328/CTPL/MC
Policy No. D-18088936MFSH
Accident Date 03/03/2020
Inspection Date 05/03/2020

| Description | Total |
|---------------------|---------------|
| Survey Inspection | 580.00 |
| Resurvey Inspection | |
| Digital Photographs | |
| Transportation | |
| Subtotal | 580.00 |
| GST (7%) | 40.60 |
| Grand Total | 620.60 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC6/FCI20003595/Uda3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 17-08-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|------------------|-----------------------|------------|
| Insured Veh. | SHC 3680G | Veh. Inspected | SKN 628K |
| Policy No. | D-18088936MFSH | Coverage (\$) | 0.00 |
| Claim No. | D20/1328/CTPL/MC | Excess (\$) | 0.00 |
| Assign From | RACHEL WU | Assign Date | 05/03/2020 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|------------------|---------------------|------------|
| Make & Model | NISSAN GT-R 3.8A | c.c | 3799 |
| Engine No. | HIDDEN | Year of Reg. | 2008 |
| Chassis No. | R35002067 | Colour | WHITE |
| Odometer | 123546 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|-------------|----------|---------|
| R/H Front Tyre | 255/40Z R20 | MICHELIN | 6 mm |
| L/H Front Tyre | 255/40Z R20 | MICHELIN | 6 mm |
| R/H Rear Tyre | 285/35Z R20 | MICHELIN | 6 mm |
| L/H Rear Tyre | 285/35Z R20 | MICHELIN | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|-----------------------|---|------------------------|------------|
| Accident Date | 03/03/2020 | Inspection Date | 05/03/2020 |
| Survey held at | FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 628K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | HEADLAMP N/S | HOLDER CRACKED | 6,500.00 | 3,600.00 |
| 1 | FRONT FENDER N/S | TO REPAIR SEE LABOUR | 2,900.00 | - |
| 1 | FRONT FENDER INNER SHIELD N/S | TORN | 331.00 | 322.20 |
| 1 | FRONT BUMPER REINFORCEMENT | NOT NECESSARY | 2,500.00 | - |
| | LESS 10% DISCOUNT | | - | -392.22 |
| | | | 12,231.00 | 3,529.98 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | FRONT BUMPER SPORT TYPE (FIBRE) (SN) | TORN | 8,000.00 | 6,500.00 |
| 1 | FRONT BUMPER LOWER SKIRTING (CARBON) (SN) | TORN / CRACKED | 6,800.00 | 1,000.00 |
| 1 | SET FRONT BUMPER BLACK STICKER (SN) | NOT NECESSARY | 350.00 | - |
| 1 | FRONT BUMPER LED LAMP N/S (SN) | NOT NECESSARY | 320.00 | - |
| 1 | FRONT BUMPER LOWER TRAY COVER (SN) | TORN | 1,200.00 | 550.00 |
| 1 | FRONT SPORT RIM '22' INCH N/S (SN) | NOT NECESSARY | 3,800.00 | - |
| | | | 20,470.00 | 8,050.00 |
| <u>LABOUR</u> | | | | |
| | TO CHECK WIRING . | | 80.00 | 20.00 |
| | TO CONDUCT WHEEL ALIGNMENT . | NOT NECESSARY | 150.00 | - |
| | TO SPRAY RUST PROOFING . | NOT NECESSARY | 50.00 | - |
| | TO DIAGNOSE & REPROGRAMME SYSTEM. | | 380.00 | 50.00 |
| | LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER N/S . | | 800.00 | 500.00 |
| | TO PUTTY & SPRAY PAINTING. | | 800.00 | 400.00 |
| | | | - | - |
| | | | - | - |
| | | | - | - |
| | | | 2,260.00 | 970.00 |
| GRAND TOTAL | | | 34,961.00 | 12,549.98 |



| | | | |
|---|--|--|------------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 10,000.00 |
|---|--|--|------------------|

Report Ref No. CC6/FCI20003595/Uda3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 628K

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payco Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 628K

RE-INSPECTION

