

NSI/INC 20003599/TISf3
INC

ASS. REC. BY: Tanphm

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. MT/1086724-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHB 1005A Yr Regn: 2014 May
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius Hybrid c.c. 1798
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 819830 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: STDKN36U405741826
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: 20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Newton
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 2/3/20
 Survey held at SMART
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	no Policy
	SHB 1005A - (03) (112002257/GKAB DUA-03/02/2020
	SJZ 8601H - X
23/3	Emerl Poln Sum 4/5 \$2200, 4 days (\$ 5,405.92 Red - 71%)
	<u>30/3/2020</u>

Date/Time, File Pass to? 01/04/20
 1) Typist
 Date/Time, File Return to?
 2) _____
 Plan of Format:
Lump Sum / L.P. : \$ 2,200 / 45

Days Of Repair: 4
 Resurvey No. of Trip: 2
 Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	

TAX 02/20/2018
 INC SJZ 8601H

Enquire Transaction History

UU; @UU; ¼@

Log Date/Time: 02 Mar 2020 / 12:09:58

Asset Type: Vehicle

Asset ID: SJZ8601H

Transaction Type: 18.32 Insurance Enquiry (GIRO Payment)

User ID: ESASBAHQ - BALQISH BINTE ABDUL HALIM

Transaction Amount: \$7.49

Channel: External Agency

Business Transaction Reference No.: 20200302120958042948

Search Date / Time: 29 Feb 2020 18:20:00

Insurance Company: NTUC INCOME INS CO-OP LTD

Information displayed is correct as at the log date and time.

[Enquire Related Logs](#)

[Back to List](#)

TP Claims against NTUC Income: Follow-Through Survey

Date : 31/03/2020

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1	MT/1086724-002	SMRT TAXIS PTE LTD	SHB 1005A	SIZ 8601H	29/02/2020	18:20	\$ 7,605.92	\$ 2,200.00

Shirley Hiew (LKK Auto)

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 23 March 2020 11:46 am
To: Taufikh (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SHB1005A

Hi,

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

-----Original Message-----

From: Taufikh (LKK Auto) [mailto:taufikh@lkkauto.com]
Sent: Monday, 23 March 2020 11:21 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Cc: 'Shirley Hiew (LKK Auto)'
Subject: RE: SHB1005A

Hi Poh Suan,

COR l/s\$2200 , 4 days.

Regards
Taufikh
Lkk Auto

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [mailto:YeoPohsuan@smrt.com.sg]

Sent: Friday, 20 March 2020 2:30 PM
To: Taufikh (LKK Auto)
Cc: sur@lkkauto.com; cs-a@lkkauto.com
Subject: SHB1005A

Hi Taufikh,

Attached herewith the repair estimate of SHB 1005A having Case No:
TAX/02/20/2098.

There is no change to the approved amount of \$2,200 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards

L1019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

9749 Madfikh

ACCIDENT STATEMENT

Date Of Report	02/03/2020 09:15
Date Of Accident	29/02/2020 18:20
Exact Location Of Accident	ALEXANDRA ROAD (OUTSIDE IKEA)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1005A
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	1XXXXX369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	
Driver	
Name of Driver	LOON PENG PUI
NRIC No	SXXXX130C
Date Of Birth	29/09/1963
Occupation	OUTDOOR
Date Of Driving Pass	07/07/1988
Driving Experience	31 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 11
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

I WAS STATIONARY ALONG ALEXANDRA ROAD (OUTSIDE IKEA) AS I WAS WAITING FOR THE FRONT VEHICLE TO MOVE. WHILST STATIONARY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SJZ8601H HAD COLLIDED ONTO THE REAR OF MY TAXI. WHEN I ALIGHTED, I REALISED THAT IT WAS A CHAIN COLLISION INVOLVING 3 VEHICLES INCLUDING MINE.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: FILE TOO BIG
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJZ8601H
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver MUSTAFA LUTFI BINALI
 NRIC/Passport Number SXXXX620D
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKP2334J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver STEVE TAN WEI CHIANG
NRIC/Passport Number SXXXX516F
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)



TOWARDS
 → ALEXANDRA
 VILLAGE

- A - SHB1005A
- B - SJZ 8601H
- C - SKP 2334J

[Signature] 2/3/20

Large empty rectangular area with horizontal dashed lines, intended for a declaration or notes.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature] 2/3/20
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

[Signature] 2/3/20
 Reporting Centre Personnel's Signature
 Name:
 NRIC/PIN No.:



Case Details

Case Reference Number : TAX/02/20/2098
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1005A

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-10696-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 29/02/2020 10:20 AM
 Vehicle Age(In Months) : 69

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval		Remarks	
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	de
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	re
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	re
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	? X nn
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	? X nn
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	? X nn
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	0	0	Not Give	X nn
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	re
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	re
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace	re
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Check	? X nn
Total Spare Part Cost									5,349.05	Surveyor Total		1,134.22		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									4,279.24	Final Sur Total		907.38		

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.26	Replace	0	0	Check	X n n
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give	X n n
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	X n n
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace	Aut
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0	Not Give	X n n
One Time Key In	Main			UNDER COVER RR SHIELD	1	63.90	63.90	25.00	47.92	Replace	0	0	Not Give	X n n
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	0	Repair	Rto
One Time Key In	Main			TAILGATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	0	0	Not Give	X n n
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	0	0	Not Give	X n n
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	nk
One Time Key In	Main			NAME PLATE (PRUIS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace	nk
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace	nk
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	nk
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	nk
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0	Not Give	X n n
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0	Not Give	X n n

Total Spare Part Cost 5,349.05

Surveyor Total 1,134.22

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 4,279.24

Final Sur Total 907.38

SMRT Recommendation										Surveyor Approval			Remarks	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)		Repair/Replace
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	all X
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	X M
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	0.00	548.40	Replace	0	0	Not Give	X M
Total Spare Part Cost									5,349.05	Surveyor Total			1,134.22	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)			20	
Final Spare Part Cost									4,279.24	Final Sur Total			907.38	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	250	
Total:			507.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
3	Main	TO RESPRAY TAIL GATE	378.00	200	
4	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	
5	Main	TO RESPRAY REAR SPOILER	180.00	0	
Total:			1,296.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	0	
2	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	
3	Main	TO REPLACE SUNDRY PARTS	100.00	20	
4	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30	
Total:			480.00	80.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
5	Major	TO WASH AND VACUUM	80.00	0	
Total:			480.00	80.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	4,279.24	907.38
Total Labour Cost	907.00	250.00
Total Spray Painting	1,296.00	400.00
Other	480.00	90.00
Overall Total	6,562.24 7605.92	1,654.22
Lump Sum Repair Option		✓
Lump Sum Total	6,550.00	1,650.00
Surveyor Approved Amount		1,650.00
No of Repair Days*	5	2
Remarks		Resurvey after repair
Surveyor Name		Taufik
Signature		
Survey Date	02/03/2020	05/3/2020

Save Clear

Taufik 97415749
- WP

2/3/20

Resurvey after repair
02 days

A sur C (Insurance) was

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 60 Woodlands Industrial Park East, Singapore
 FAX Number: 63824552
 Estimator Telephone Number: 68660073
 Accident Reporting Number: 63827477

Date Generated: 20/03/2020
 User ID: RonSuan

Section A - Accident Details

Registration Number	SHB1005A
Case Reference Number	TAX/02/20/209a
Registration Date	11/5/2014
Company Type	SMRT Taxis Pte Ltd
Make?	TOYOTA
Model	PRIUS
Name of Driver	LOON PENG PUI
Type of Accident	Head to Rear
Accident Date and Time	29/2/2020 6:20 PM
Accident Reported Date and Time	2/3/2020 9:20 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105971
Special instruction to ARC, if any	TP / REAR PORTION
Completed Date and Time	2/3/2020 1:41 PM
Crossis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$807.00	\$450.00
Total Spray Cost	\$1,676.00	\$700.00
Total Spare Part Cost	\$5,727.72 4642.92	\$1,490.12
Total Other Cost	\$480.00	(\$440.12)
TOTAL COST	\$8,673.72 7605.92	\$2,200.00 (L/S)
Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Approved / Adjusted By	Ang Bang Kien	Taufikh (LKK) / NTUC
ARC Surveyor Sign Off Date	06/03/2020 10:16 AM	05/03/2020 11:24 AM
Signature		
Remarks	Total number of repair days = 4 days. SUP = + 2 days.	Resurvey after repair



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
 20 Woodlands Industrial Park E4 Singapore
 Phone: 63625592
 FAX Number: 63655592
 Estimator Telephone Number: 63625592
 Accident Reporting Number: 63625592

Date Generated: 20/03/2020

User ID: FohSuan

Section C - Quotation and Accident Invoice Details

Quotation Number	ON-2003-0355	Invoice Number	
Quotation Date	20/03/2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$507.00	\$250.00
TO REPAIR REAR END PANEL	\$300.00	\$200.00
Total Labour	\$807.00	\$450.00

Part 2 - Spray Painting & Panel Beating Related Works


Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RE SPRAY REAR BUMPER	\$378.00	\$200.00
TO RE SPRAY BUMPER BEAM	\$180.00	\$0.00
TO RE SPRAY TAIL GATE	\$378.00	\$200.00
TO RE SPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$0.00
TO RE SPRAY REAR SPOILER	\$180.00	\$0.00
TO RE SPRAY BUMPER BEAM	\$180.00	\$100.00
TO RE SPRAY REAR PANEL	\$200.00	\$200.00
Total Spray Painting & Panel Beating	\$1,676.00	\$700.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO TEST AND RE-FIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$520.09)
Total Other Costs	\$480.00	(\$440.09)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check
		52015-47050	ARM SUB-ASSY RH BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check
		52015-47030	ARM SUB-ASSY RH BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
50 Woodlands Industrial Park 14, Singapore
Tax Number: 4366552
Kilometer Telephone Number: 64662031
Accident Reporting Number: 58662672

Date Generated: 20/03/2020
User ID: PuhSuan

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace ✓
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace ✓
		52592-47021	BUMPER SEAL RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Check ✓
		52591-47021	BUMPER SEAL RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check ✓
		76088-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given ✓
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Not Given ✓
		76891-47020	BUMPER LIP REAR	1.00	\$228.90	25.00	\$171.68	Replace	Replace ✓
		58308-47011	UNDER COVER SUB-ASSY RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given ✓
		51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given ✓
		67005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair ✓
		75574-47020	TAILGATE DOOR GLASS MOULDING RH	0.00	\$29.40	0.00	\$0.00	Replace	Not Given ✓
		76801-47070.030	TAILGATE OUTSIDE GARNISH	0.00	\$504.90	0.00	\$0.00	Replace	Not Given ✓
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
		75442-47030	NAME PLATE (PRUIS)	1.00	\$60.80	25.00	\$45.60	Replace	Replace ✓
		75443-47030	NAME PLATE (TOYOTA)	1.00	\$51.90	25.00	\$38.93	Replace	Replace ✓
			SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace ✓
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	Replace ✓
		76085-47910	SPOILER REAR	0.00	\$953.70	0.00	\$0.00	Replace	Not Given ✓
		61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given ✓
			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given ✓
			STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given ✓
		81561-47170	TAIL LAMP LH	0.00	\$548.40	0.00	\$0.00	Replace	Not Given ✓
Total					\$6,719.30		\$1,126.44		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
		52015-47050	ARM SUB-ASSY RH BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
		52016-47030	ARM SUB-ASSY RH BUMPER LH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
Total					484.90		363.68		

Abt -
Abt -
Abt -

1490.12
+ 450.00
+ 780.00

2720.12
- 202

2518.12

1490.12
L/S \$2200/-
4 days

07