

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI20003603/R1VF3Q2**Date:** 29/10/2020REFERENCEHandling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN19261719000

**Claimant  
Vehicle No :** SKW6748K**Insured Vehicle  
No :** GBJ6082Y

Date of Loss: 02/03/2020

Nature of Claim: TP

Claim  
No: SNM20D201128DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKW6748K**

Make &amp; Model: TOYOTA WISH, 1.8 (A)

Engine No: 2ZR1668256

Reg. Date: 11/11/2015 (Man. Year: 2015)

Chassis No: JTDGG20W00J003145

Colour: Gold

Odometer: 171138 km

Engine Capacity: 1798 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	990.00	990.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	852.00	610.00	242.00	28.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,842.00</b>	<b>1,600.00</b>	<b>242.00</b>	<b>13.14</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>128.94</b>	<b>112.00</b>	<b>16.94</b>	<b>13.14</b>
<b>Nett Amount (S\$)</b>	<b>1,970.94</b>	<b>1,712.00</b>	<b>258.94</b>	<b>13.14</b>

INSPECTION

Date of Assignment: 06/03/2020

Date Inspected: 05/03/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 1.0 days

**Adjuster:** MOHD RASUL**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 27 Oct 2020)
<b>Parts:</b> M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKW6748K)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR ASSEMBLY RH	Cracked	990.00 FS	*990.00 FS
					<b>Total Parts (S\$)</b>	<b>990.00</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER RHS FROT DOORS MULTI-LOCK SYSTEM, POWER WINDOW DEVICES AND WING MIRROR ASSY	New	360.00	360.00
2	TO RESPRAY SIDE MIRROR COVER	New	300.00	150.00
3	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	100.00
<b>Gross Labour Cost (S\$)</b>			<b>852.00</b>	<b>610.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >