

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20003607/KGS3Q2

Date: 30/06/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SHC5861M	Insured Vehicle No :	SHD3601E
Date of Loss: 02/03/2020	Nature of Claim: TP	Claim No: MCT20030008

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5861M		
Make & Model:	RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C002310
Reg. Date:	11/12/2014 (Man. Year: 2014)	Chassis No:	VF1ABL15AUC280930
Colour:	Metallic White/Red	Odometer:	591138 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,491.55	2,326.29	22,165.26	90.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,350.00	1,210.00	18,140.00	93.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,841.55	3,536.29	40,305.26	91.93
Approved Total (Overridden) (S\$)		2,850.00		
(S\$)	43,841.55	2,850.00	40,991.55	93.50
+ GST 7.00/7.00% (S\$)	3,068.91	199.50	2,869.41	93.50
Nett Amount (S\$)	46,910.46	3,049.50	43,860.96	93.50
+ Loss of Use (5.5 x S\$40.00/day) (S\$)		220.00		
+ Car Rental (5.5 x S\$95.04/day) (S\$)		522.72		
Nett Liability (S\$)		3,792.22		
Global Sum Settlement (S\$)		3,750.00		

INSPECTION

Date of Assignment: 04/03/2020

Date Inspected: 04/03/2020 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2020)
Parts:	143	RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5861M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Dented / Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Distorted	100.90 FL	*100.90 FL
13	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	401.40 FL	*- FL
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
19	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL
26	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL
27	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL
28	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
29	1		*BOOT HINGE RH	Repair	253.80 FL	*- FL
30	2		*BOOT RUBBER PLUG	Serviceable	139.90 FL	*- FL
31	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- FL
32	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
33	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*- FL
34	1		*BOOT LOCK	Repair	246.60 FL	*- FL
35	1		*BOOT SWITCH	Serviceable	113.00 FL	*- FL
36	1		*SPARE TYRE BOARD L70Y	Serviceable	680.90 FL	*- FL
37	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,229.40 FL	*- FL
38	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
39	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL
40	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL
41	1		*KNUCKLE ARM REAR LH	Serviceable	472.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	2		*KNUCKLE HUB+BEARING LH/RH	Serviceable	272.30 FL	*- FL
43	1		*REAR AXLE	Serviceable	3,469.00 FL	*- FL
44	1		*LOWER ARM REAR LH	Serviceable	543.50 FL	*- FL
45	1		*AXLE SPRING ARM LH	Serviceable	220.60 FL	*- FL
46	1		*ABSORBER REAR	Serviceable	217.30 FL	*- FL
47	1		*STABILIZER BAR REAR	Serviceable	427.90 FL	*- FL
48	1		*STABILIZER LINK REAR	Serviceable	55.20 FL	*- FL
49	1		*SUBFRAME ARM REAR	Serviceable	198.33 FL	*- FL
50	1		*RODE -LONG REAR	Serviceable	120.16 FL	*- FL
51	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
52	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
53	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
54	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
55	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
56	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
57	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
58	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
59	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
60	1		*BOOT STICKER TRANS-CAB	Not Necessary	35.00 FS	*- FS
61	1		*BOOT STICKER 6555-3333	Not Necessary	35.00 FS	*- FS
62	2		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
63	1		*WINDSCREEN MOULDING	Not Necessary	150.00 FS	*- FS
64	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
65	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
66	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
67	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
68	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
69	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*30.00 FS
70	1		*REAR LEFT TYRE	Serviceable	330.00 FS	*- FS
71	1		*REAR LEFT TYRE RIM	Serviceable	385.00 FS	*- FS
72	1		*EXHAUST MOUNTING REAR	Serviceable	16.00 FS	*- FS
73	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	100.00 FS	*- FS
74	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
75	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **26,869.26** **2,563.10**
- List Item Discount on L Items 10.00/10.00% (\$\$) **2,377.71** **236.81**

Total Parts (\$\$) **24,491.55** **2,326.29**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	7,500.00	600.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	60.00
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
5	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
12	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
13	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
14	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
15	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
16	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	440.00
17	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
18	TO DISMANTLE AND REFIT REAR AXLE ASSY ,REMOVE AND RENEWAL OF PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
19	TOWING FEES	New	150.00	0.00
20	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
Gross Labour Cost (\$\$)			19,350.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >